

Vehicle Inspection Report

Date Inspected: 22/04/2025 09:40

Reg: HJ13HLA

VIN: WV2ZZZ7HZDH069325

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	VOLKSWAGEN	Body Type	MPV	Doors	5
Model	CARAVELLE	Fuel Type	Diesel	Colour	Blue
	BUSINESS TDI AU - 1968cc	Transmission	Auto	Year of MFR	2013
Mileage	175,950 miles			Date First Reg	27/03/2013

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	13/02/2026
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	6 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service History
Stamps


Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	Yes	Number of Seats	6	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Bonnet
Chipped
1 To 5
Smart Repair

Door nsf
Scratched
Over 25mm Not

Wing nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Wing nsf

Chipped
1 To 5
Smart
Repair



Door nsr

Chipped
Multiple
Chips
Refinish



Bumper
Rear

Scratched

25 to
100mm
Thru Paint

Smart
Repair



Boot Lid

Dented

2 Or Less
UpTo
10mm

Smart
Repair



Door osr

Chipped

Multiple
Chips
Refinish

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Thru Paint

Machine
Polish

Qtr Panel
nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Bumper
Rear

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Qtr Panel
osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsf

Chipped
1 To 5
Smart
Repair



Qtr Panel
nsr

Dented

Over
30mm

Repair
and
Refinish

Boot Lid

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Qtr Panel
osr

Chipped
1 To 5
Smart
Repair



Door osf

Dented

2 Or Less
UpTo
10mm

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Chipped	Multiple Chips	Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Door osr	Chipped	Multiple Chips	Refinish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	2 Or Less UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

The diagram shows a top-down view of a vehicle with various components labeled. The labels are as follows:

- S2**: Left side door area.
- D2**: Left side rear door area.
- D1**: Left side front door area.
- C2**: Left side rear wheel area.
- C2**: Left side front wheel area.
- C2**: Left side rear fender area.
- C2**: Left side front fender area.
- D1**: Left side rear door area.
- D1**: Left side front door area.
- C2**: Left side rear wheel area.
- C2**: Left side front wheel area.
- C2**: Left side rear fender area.
- C2**: Left side front fender area.
- S3**: Right side door area.
- D1**: Right side rear door area.
- D1**: Right side front door area.
- C2**: Right side rear wheel area.
- C2**: Right side front wheel area.
- C2**: Right side rear fender area.
- C2**: Right side front fender area.

Splat Key

S2	Scratch/Paint defect 30-100mm
S3	Scratch/Paint defect 100m +
D1	Dent/damage under 30mm
D2	Dent/damage 30-100mm
C2	Multiple Chips

Comments

Last Service - 08/07/2021 at 149,060 miles (11 SERVICES)

broken headlight

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.