

# **VEHICLE INSPECTION REPORT**

KY110BF

## Mazda 6 2.0 Takuya 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	TBC		
Details					
Reg. date	01/03/2011	VIN	JMZGHA4E601426634	CAP Average	£530.00
Year	2011	Body Style	Hatchback	CAP Below	£250.00
Mileage	159,158 Miles Warranted	Keys	2	Gearbox	MANUAL
		MOT Due	18/12/2025	Gears	6
Fuel Type	Petrol	CAP Clean	£920.00	Doors	5
Colour	RED				


### £100 ADDITIONAL FEE. Front lights cloudy

Tyres			
NSF	SUNNY	3.0mm	
NSR	UNIROYAL	2.0mm	
OSF	UNIROYAL	2.0mm	
OSR	UNIROYAL	3.0mm	
Spare			

### **Features**

#### Cruise control • PAS Rear parking sensor • Rear wiper Steering wheel mounted controls Audio remote control Electric door mirrors Front armrest Front armrest Radio/CD Body coloured bumpers Climate control Height adjustable drivers seat Metallic Paint Towbar Front electric windows Air conditioningFront head restraints Rear electric windows ABS • Rear armrest Rear headrests • 3x3 point rear seat belts Isofix child seat anchor points Drivers airbag Side airbagsPartial leather seat trim Passenger airbagRemote central locking Traction controlAlloy wheels Central locking

## **Condition Check**



## **Damage Photos**



1: Boot Lid Scratched Over 25mm Not Thru Paint

2: Bumper Rear Scratched Over 100mm Thru Paint



4: Qtr Panel osr

3: Wheel osr Scratched Over 50mm





5: Door osr Dented Over 30mm



7: Wing osf Chipped Multiple Chips





8: Bumper Front Scratched 25 to 100mm Thru Paint

# No Image

9: Bumper Front Scratched Over 25mm Not Thru Paint




10: Bonnet Chipped 1 To 5



# No Image

11: Wheel nsf Scratched Over 50mm





13: Door nsf Dented Over 2 UpTo 10mm



14: Door nsr Chipped 1 To 5





15: Qtr Panel nsr Poor Previous Repair Poor Paint



17: Roof Dented Between 10mm + 30mm

Interior

Carpet Condition Seat Condition Average Poor 18: Seat Back Cover osf Torn Over 3mm

Scratched

Upholstery Condition Odour

Average No