



# VEHICLE INSPECTION REPORT

**WF59KWG**

## Citroen C4 Picasso 1.6HDi 16V VTR Plus 5dr [5 Seat]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	28/09/2009	Keys	4	CAP Clean	£400.00
Year	2009	Service history	Yes	CAP Average	£200.00
Mileage	143,998 Miles Warranted	Service documents	Printout	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	4	Gearbox	MANUAL
Colour	BLUE	Last service date	22/07/2024	Gears	5
VIN	VF7UD9HZC9J158100	Last service miles	137,132		
Body Style	MPV	MOT Due	28/02/2026		

£50 ADDITIONAL FEE.

Last Service - 22.07.2024 at 137132 miles (4 services) Parking sensor fault

### Tyres

NSF	NEXEN	4.0mm
NSR	HANKOOK	Worn
OSF	NEXEN	4.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Bumper Rear  
Dented  
With Paint Damage



2: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



3: Qtr Panel nsr  
Dented  
With Paint Damage



4: Wheel nsr  
Scratched  
Over 50mm




5: Door nsr  
Chipped  
1 To 5



6: Door nsr  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Chipped  
1 To 5



8: Door nsf  
Scratched  
Over 25mm Not Thru Paint

No Image



9: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsf  
Scratched  
Over 50mm



11: Bonnet  
Chipped  
1 To 5



12: Bumper Front  
Scratched  
Over 100mm Thru Paint



13: A Post ns  
Poor Previous Repair  
Paint Flake



14: A Post os  
Rusted  
Over 5mm

No Image



15: Wing osf  
Scratched  
Over 25mm Not Thru Paint

16: Wheel osf  
Scratched  
Over 50mm

No Image



17: Door osf  
Scratched  
Over 25mm Not Thru Paint

18: Door osr  
Dented  
With Paint Damage



19: Qtr Panel osr  
Dented  
With Paint Damage



20: Wheel osr  
Scratched  
Over 50mm

No Image

No Image

21: Tyre nsr  
Worn  
Replace

22: Tyre nsr  
Worn  
Replace

### Interior

**Carpet Condition**      Average  
**Seat Condition**      Poor

**Upholstery Condition**      Average  
**Odour**      -

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK