

Vehicle Inspection Report

Date Inspected: 25/04/2025 11:37

Reg: LD57BYN

VIN: VF7CHNFUC25995722

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	CITROEN	Body Type	MPV	Doors	5
Model	XSARA PICASSO	Fuel Type	Petrol	Colour	Grey
	DESIRE 16V - 1587cc	Transmission	Manual	Year of MFR	2007
Mileage	89005 miles	Gears	5	Date First Reg	29/09/2007

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	No
NSF Depth	4 mm	Tools	No
OSR Depth	5 mm	Spare	No Spare
NSR Depth	3 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No  
History  
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No

**Door osf**

Scratched  
Over  
25mm  
Thru Paint  
Refinish

**Door osr**

Chipped  
1 To 5  
Smart  
Repair

**Door osr**


Dented  
2 Or Less  
UpTo  
10mm  
Smart  
Repair

**Qtr Panel  
osr**

Dented  
Between  
10mm +  
30mm  
Smart  
Repair

**Bumper  
Rear**

Scratched  
Over  
100mm  
Thru Paint  
Refinish

**Lamp nsr**

Broken  
Needs  
Replaced  
Replace

**Qtr Panel  
nsr**

Scratched  
Over  
25mm  
Thru Paint  
Refinish

**Door nsr**

Scratched  
Over  
25mm  
Thru Paint  
Refinish

**Door nsf**

Scratched  
Over  
25mm  
Thru Paint  
Refinish

**Door  
Mirror  
Assy nsf**

Broken  
Needs  
Replaced  
Replace

**Wing nsf**

Hole  
Over  
10mm  
Replace

**Bumper  
Front**

Scratched  
Over  
100mm  
Thru Paint  
Refinish

**Bonnet**

Chipped  
1 To 5  
Smart  
Repair

**Screen  
Front**

Chipped  
UpTo  
10mm  
Smart  
Repair

**Seat  
Base  
Cover  
osf**

Holed  
UpTo  
3mm  
Smart  
Repair

Damage Lines			
Component	Condition	Severity	Repair
Door osf	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Chipped	1 To 5	Smart Repair
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Lamp nsr	Broken	Replace	Replace
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Scratched	Over 25mm Thru Paint	Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Wing nsf	Hole	Over 10mm	Replace
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Seat Base Cover osf	Holed	UpTo 3mm	Smart Repair

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**C2**  
Multiple Chips

**X**  
Req Replacement

Comments
<p>engine whine when engines reved,drivers door doesnt open from inside,oil leaking round engine,rear bumper out of line</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>