

Vehicle Inspection Report

Date Inspected: 28/04/2025 09:41

Reg: AU69YBO

VIN: NMTKZ3BXX0R329021

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	TOYOTA	Body Type	Hatchback	Doors	5
Model	C-HR EXCEL HEV CVT - 1798cc	Fuel Type	Hybrid	Colour	White
Mileage	66,203 miles	Transmission	Auto	Year of MFR	2019
				Date First Reg	09/09/2019

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	08/09/2025
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	6 mm	Tools	No
NSR Depth	6 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service Yes
History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment

Bumper
Rear

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper
Rear

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Bonnet

Scratched

Over
25mm Not

Qtr Panel
nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Screen Front

Chipped
UpTo 10mm
Smart Repair

Thru Paint
Machine Polish



Bonnet
Chipped
1 To 5
Smart Repair

Bumper Front

Chipped
Multiple Chips
Smart Repair

Bumper Front

Scratched
Over 25mm Not Thru Paint
Machine Polish

Wing osf

Scratched
Over 25mm Not Thru Paint
Machine Polish



Wing osf

Chipped
1 To 5
Smart Repair

Door osf

Scratched
Over 25mm Not Thru Paint
Machine Polish

Door osf

Chipped
1 To 5
Smart Repair

Door osr

Scratched
Over 25mm Not Thru Paint
Machine Polish

Qtr Panel osr

Scratched
Over 25mm Not Thru Paint
Machine Polish

Door nsr

Scratched
Over 25mm Not Thru Paint
Machine Polish

Door nsf

Scratched
Over 25mm Not Thru Paint
Machine Polish

Wing nsf

Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsf

Chipped
1 To 5
Smart Repair



Door nsr

Dented
2 Or Less UpTo 10mm
Smart Repair




Qtr Panel nsr

Chipped
1 To 5
Smart Repair

Damage Lines

Component	Condition	Severity	Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel nsr	Chipped	1 To 5	Smart Repair

Vehicle Splat



Splat Key

S2
Scratch/Paint defect 30-100mm
D1
Dent/damage under 30mm
C2
Multiple Chips
PP
Poor Previous

Comments

Last Service - 20/11/2021 at 11,952 miles (2 MAIN DEALER SERVICES)

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.