



VEHICLE INSPECTION REPORT

KN15GZO

Citroen C4 Picasso 1.6 HDi VTR+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/03/2015	Body Style	MPV	Last service miles	71,216
Year	2015	Keys	2	CAP Clean	£2,375.00
Mileage	84,170 Miles Warranted	Service history	Yes	CAP Average	£1,925.00
Fuel Type	Diesel	Service documents	Service Book	CAP Below	£1,500.00
Colour	BLUE	Number of stamps	7	Gearbox	MANUAL
VIN	VF73D9HP0FJ548082	Last service date	23/05/2023	Gears	5

£100 ADDITIONAL FEE. EXPIRED MOT. Last service 23/05/2023 @ 71216 miles (8 SERVICES 2 MAIN DEALER) book & print Clutch issues

Tyres


NSF	PIRELLI	Worn
NSR	NEXEN	3.0mm
OSF	PIRELLI	3.0mm
OSR	BUDGET	2.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Telephone
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
Over 30mm



9: Wheel nsr
Corroded
Light



10: Bumper Rear
Poor Previous Repair
Rippled UpTo 30%



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Chipped
1 To 5



13: Door osr
Chipped
1 To 5



14: Door osf
Chipped
1 To 5



15: Wheel osf
Scratched
Over 50mm

16: Tyre nsf
Worn
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK