

### **VEHICLE INSPECTION REPORT**

**HG13CNY** 

### BMW 5 Series 520d M Sport 4dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape Crape
		V5	Present		
Details					
Reg. date	28/06/2013	Keys	2	CAP Clean	£4,750.00
Year	2013	Service history	Yes	CAP Average	£4,175.00
Mileage	76,642 Miles Warranted	Service documents	Printout	CAP Below	£3,625.00
Fuel Type	Diesel	Number of stamps	1	Gearbox	MANUAL
Colour	BLACK	Last service date	24/03/2016	Gears	6
VIN	WBAFW12070DV83670	Last service miles	25,190	Doors	4
Body Style	Saloon	MOT Due	08/08/2025		

£100 ADDITIONAL FEE Last service 24/03/2016 @ 25190 miles (1 MAIN DEALER SERVICE) Both headlights have condensation

T	y	re	S
---	---	----	---

NSF	RAPID	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	Worn
OSR	BUDGET	4.0mm
Spare		

#### **Features**

- · Bluetooth connection
- · Navigation system
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests · Drivers airbag
- Central locking

- Cruise control
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- · Front parking sensor
- Rear parking sensor Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- · Heated front seat
- Steering wheel mounted controls
  Electric door mirrors
- Front electric windows
- · Rear electric windows
- ABS
- Traction control
- Alloy wheels

#### **Photos**










### **Condition Check**



#### **Damage Photos**



1: Bumper Rear Scratched Over 100mm Thru Paint No Image

2: Boot Lid Scratched Over 25mm Not Thru Paint



3: Qtr Panel nsr Dented Over 2 UpTo 10mm

4: Qtr Panel nsr Scratched Over 25mm Not Thru Paint



5: Wheel nsr Scratched Over 50mm



6: Door nsr Chipped 1 To 5

# No Image





8: Door nsf Scratched Over 25mm Thru Paint



9: Wheel nsf Scratched Over 50mm



10: Wing nsf Chipped 1 To 5

11: Wing nsf Scratched Over 25mm Not Thru Paint



12: Bonnet Chipped Multiple Chips



13: Bumper Front Scratched Over 100mm Thru Paint



14: Wing osf Chipped 1 To 5

15: Wing osf Scratched Over 25mm Not Thru Paint



17: Door osf Chipped 1 To 5



19: Door osr Chipped 1 To 5



16: Wheel osf Scratched Over 50mm

## No Image

18: Door osf Scratched Over 25mm Not Thru Paint

# No Image

20: Door osr Scratched Over 25mm Not Thru Paint



21: Qtr Panel osr Scratched UpTo 25mm Thru Paint

22: Qtr Panel osr Scratched Over 25mm Not Thru Paint



23: Wheel osr Scratched Over 50mm

## No Image

24: Tyre osf Worn Replace

# No Image

25: Tyre osf Worn Replace

Interior

**Carpet Condition Seat Condition** 

Average Average **Upholstery Condition Odour** 

Average No

#### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test OK
Brakes OK	Clutch Slip Test from Static OK
Turbo Boosting OK	Gearbox Static Gear Selection (engine running) OK
Parking Brake OK	No Excessive Smoking OK
EML light illuminated OK	Oil warning light illuminated OK
Airbag light illuminated OK	DPF light illuminated OK
ABS light illuminated OK	Service indicator light illuminated OK
Windows OK	Radio OK
Sat nav OK	Steering OK