

Vehicle Inspection Report

Date Inspected: 11/02/2025 10:22

Reg: VU21WRN

VIN: VF3MCYHZMMS018494

NAMA Grading



Grade

1

Appraised By: Eastbourne Car Auctions

General Details

Make	PEUGEOT	Body Type	Hatchback	Doors	5
Model	5008 ACTIVE PREMIUM BLUEH - 1500cc	Fuel Type	Diesel	Colour	Bronze
		Transmission	Manual	Year of MFR	2021
Mileage	77,802 miles	Gears	6	Date First Reg	10/05/2021

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	No Spare

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Average
Parcel Shelf	No
Odour	No
Comments	seats stained

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	Yes
Keyless Entry	No	Towbar	No	Number of Seats	7	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Bonnet

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsr

Dented

Between
10mm +
30mm

Smart
Repair



Bumper
Rear
Moulding

Scuffed
(Unpainted)

Over
100mm

Smart
Repair

Door osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bonnet

Chipped

1 To 5

Smart
Repair

Bumper
Front

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Qtr Panel
nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Bumper
Rear

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper
Front

Chipped

Multiple
Chips

Smart
Repair

Door nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Boot Lid

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Qtr Panel
osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper
Front

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Dented	Between 10mm + 30mm	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D1
Dent/damage under 30mm

C2
Multiple Chips

SC
Scuff

Comments
<div>light on dash</div> <div> <div>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</div> </div>