

Vehicle Inspection Report

Date Inspected: 24/04/2025 10:30

Reg: GX16NZK

VIN: YV1LFA4BCG1072570

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	VOLVO	Body Type	Estate	Doors	5
Model	XC90 INSCRIPTION D5 AWD A - 1969cc	Fuel Type	Diesel	Colour	Black
Mileage	83,952 miles	Transmission	Auto	Year of MFR	2016
				Date First Reg	02/03/2016

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	6 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	Yes
Keyless Entry	No	Towbar	No	Number of Seats	7	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bumper Rear

Scratched

25 to 100mm Thru Paint

Smart Repair

Qtr Panel osr

Scratched

Over

Bumper Rear

Scratched

Over 25mm Not Thru Paint

Machine Polish



Boot Lid

Scratched

Over 25mm Thru Paint Refinish

Door osr

Scratched

Over 25mm Not

25mm Not
Thru Paint

Machine
Polish



**Qtr Panel
osr**

Dented

2 Or Less
UpTo
10mm

Smart
Repair

Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Wing osf

Chipped

1 To 5

Smart
Repair



**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair



Bonnet

Chipped

1 To 5

Smart
Repair



**Bumper
Front**

Scratched

25 to
100mm
Thru Paint


Smart
Repair

**Bumper
Front**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Wing
Front
Arch
Extension
ns**

Scratched
(Painted)

Over
25mm
Thru Paint

Smart
Repair

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf

Chipped

1 To 5

Smart
Repair

Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door nsr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsr

Dented

2 Or Less
UpTo
10mm

Smart
Repair



**Qtr Panel
nsr**

Dented

2 Or Less
UpTo
10mm

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing Front Arch Extension ns	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel nsr	Dented	2 Or Less UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

C2
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE</p> <p>.</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>