

Vehicle Inspection Report

Date Inspected: 28/04/2025 17:15

Inspected By: toby

Reg: FD67KBF

VIN: W0VPD9EC6J1080951

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	VAUXHALL	Body Type	MPV	Doors	5
Model	ZAFIRA TOURER DESIGN TURB - 1364cc	Fuel Type	Petrol	Colour	Red
		Transmission	Manual	Year of MFR	2017
Mileage	43,233 miles	Gears	6	Date First Reg	20/12/2017

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	02/04/2026
No. Keys	2

Tyres & Wheels

OSF Depth	2 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	3 mm	Tools Spare	No
NSR Depth	2 mm		No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	Yes	Number of Seats	7	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	Yes

Damage Assessment



Bumper Rear
Scratched
25 to 100mm Thru Paint
Smart Repair

Bumper Rear
Scratched
Over 25mm Not Thru Paint
Machine Polish



Boot Lid
Scratched
Over 25mm Thru Paint
Refinish



**Qtr Panel
nsr**

Dented

With Paint
Damage

Repair
and
Refinish



Door nsr

Scratched

Over
25mm
Thru Paint

Refinish



Door nsf

Dented

With Paint
Damage

Repair
and
Refinish

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf

Chipped

1 To 5

Smart
Repair



**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair



Bonnet

Chipped

1 To 5

Smart
Repair

**Bumper
Front**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Front**

Chipped

Multiple
Chips

Smart
Repair

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osf

Dented

2 Or Less
UpTo
10mm

Smart
Repair



Door osr

Chipped

1 To 5

Smart
Repair

**Qtr Panel
osr**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Qtr Panel
osr**

Dented

Between
10mm +
30mm

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	2 Or Less UpTo 10mm	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair

Vehicle Splat

The diagram shows a top-down view of a vehicle with the following compartment labels:

- Front (Right): Large compartment labeled **C2**, and a smaller compartment below it labeled **C2**.
- Rear (Left): Large compartment labeled **S3**, and a smaller compartment below it labeled **S2**.
- Central Area (Top): Left compartment labeled **S3**, right compartment labeled **D2**.
- Central Area (Bottom): Left compartment labeled **C2**, right compartment labeled **D1**.

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D2
Dent/damage 30-100mm

C2
Multiple Chips

Comments

Last Service - 11/04/2023 at 28,905 miles (4 SERVICES (3 MAIN DEALER))

noisy engine and low oil pressure on dash. eml on

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.