

Vehicle Inspection Report

Date Inspected: 11/02/2025 14:51

Reg: AF68WMT

VIN: VF3MJEHZRJL073521

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	PEUGEOT	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	5008 GT LINE BLUEHDI S/S - 1997cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Grey
<b>Mileage</b>	74,388 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2018
				<b>Date First Reg</b>	08/11/2018

Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	5 mm	<b>Alloys That Need Refurb</b>	3
<b>OSR Depth</b>	6 mm	<b>Tools</b>	No
<b>NSR Depth</b>	6 mm	<b>Spare</b>	No Spare

Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No
<b>Comments</b>	seats heavily worn and car muddy

Service History

<b>Service No History Stamps</b>
----------------------------------

Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Half Leather	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	7	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	No

Damage Assessment

**Bumper Front**  
  
Scratched  
  
Over 25mm Not Thru Paint  
  
Machine Polish







**Bumper Front**  
  
Scratched  
  
25 to 100mm Thru Paint  
  
Smart Repair



**Bonnet**  
  
Chipped  
  
1 To 5  
  
Smart Repair

**Wing osf**

**Door**

	<p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>		<p><b>Mirror Assy osf</b></p> <p>Scratched (Painted)</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>		<p><b>Door osf</b></p> <p>Dented</p> <p>With Paint Damage</p> <p>Repair and Refinish</p>
	<p><b>Door osr</b></p> <p>Dented</p> <p>With Paint Damage</p> <p>Repair and Refinish</p>		<p><b>Qtr Panel osr</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>		<p><b>Bumper Rear</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>
	<p><b>Bumper Rear</b></p> <p>Scratched</p> <p>25 to 100mm Thru Paint</p> <p>Smart Repair</p>		<p><b>Boot Lid</b></p> <p>Chipped</p> <p>1 To 5</p> <p>Smart Repair</p>		<p><b>Qtr Panel nsr</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>
	<p><b>Door Moulding nsr</b></p> <p>Broken</p> <p>Needs Replaced</p> <p>Replace</p>		<p><b>Door nsr</b></p> <p>Dented</p> <p>Over 30mm</p> <p>Repair and Refinish</p>		<p><b>Door nsf</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>
	<p><b>Door nsf</b></p> <p>Dented</p> <p>Over 30mm</p> <p>Repair and Refinish</p>		<p><b>Door Mirror Assy nsf</b></p> <p>Broken</p> <p>Needs Replaced</p> <p>Replace</p>		<p><b>Door Mirror Assy nsf</b></p> <p>Broken</p> <p>Needs Replaced</p> <p>Replace</p>
	<p><b>Wing nsf</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>				

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy osf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Moulding nsr	Broken	Replace	Replace
Door nsr	Dented	Over 30mm	Repair and Refinish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Door Mirror Assy nsf	Broken	Replace	Replace
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

Comments
<p>£100 ADDITIONAL FEE</p> <p>bonnet sittig high and glovebox insecure</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>