

Vehicle Inspection Report

Date Inspected: 29/04/2025 12:38

Reg: DY69PWO

VIN: W0VZRHNS4L6004517

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	VAUXHALL	Body Type	Hatchback	Doors	5
Model	GRANDLAND X ELITE NAV TUR - 1199cc	Fuel Type	Petrol	Colour	White
Mileage	56,558 miles	Transmission	Manual	Year of MFR	2019
		Gears	6	Date First Reg	31/12/2019

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	19/01/2026
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	Inflation Kit

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment

Bumper Rear

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door nsr

Scratched

Over 25mm Not



Bumper Rear

Chipped

Multiple Chips

Smart Repair

Qtr Panel nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door nsf

Scratched

Over 25mm Not

Thru Paint
Machine
Polish



Door nsr
Chipped
1 To 5
Smart
Repair

Thru Paint
Machine
Polish

Door nsf
Chipped
1 To 5
Smart
Repair

Wing nsf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Wing nsf
Chipped
1 To 5
Smart
Repair



Screen Front
Chipped
UpTo
10mm
Smart
Repair



Bonnet
Hole
Over
10mm
Replace



Bumper Front
Scratched
25 to
100mm
Thru Paint
Smart
Repair

Bumper Front
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Wing osf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Door osf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door osf
Chipped
1 To 5
Smart
Repair

Door osr
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door osr
Chipped
1 To 5
Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bonnet	Hole	Over 10mm	Replace
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair

Vehicle Splat

The diagram illustrates a vehicle layout with the following labels:

- C2**: Located in the front passenger area, front driver area, rear passenger area, and rear driver area.
- K**: Located in the central rear area.
- S2**: Located at the front of the vehicle.

Splat Key

S2
Scratch/Paint defect 30-100mm

C2
Multiple Chips

K
Crack/Torn

Comments

Last Service - 25/07/2024 at 47,266 miles (3 MAIN DEALER SERVICES)

heavy vibration at idle and running rough . possible gearbox fault

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.