

Vehicle Inspection Report

Date Inspected: 25/04/2025 10:46

Reg: LY06CUU

VIN: VF7FCKFVC28680716

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	CITROEN	Body Type	Hatchback	Doors	5
Model	C3 SX - 1360cc	Fuel Type	Petrol	Colour	Grey
Mileage	204,980 miles	Transmission	Manual	Year of MFR	2006
		Gears	5	Date First Reg	27/05/2006

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	No
NSF Depth	4 mm	Tools	Yes
OSR Depth	4 mm	Spare	Space Saver
NSR Depth	4 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Bumper Front Moulding
Broken
Needs Replaced
Replace



Bumper Front Grill
Broken
Needs Replaced
Replace



Bonnet
Chipped
1 To 5
Smart Repair



Wing osf
Dented
Over 30mm
Repair and Refinish



Screen Front
Chipped
UpTo 10mm
Smart Repair



Door osf
Dented
With Paint Damage
Repair and Refinish



Door osr
Dented
Over 30mm
Repair and Refinish



Qtr Panel osr
Dented
With Paint Damage
Repair and Refinish



Boot Lid
Scratched
Over 25mm Not Thru Paint
Machine Polish



Bumper Rear
Poor Previous Repair
Poor Paint
Refinish



Qtr Panel nsr
Dented
2 Or Less UpTo 10mm
Smart Repair



Door nsr
Poor Previous Repair
Poor Paint
Refinish



Door nsf
Poor Previous Repair
Poor Paint
Refinish



Wing nsf
Dented
Over 30mm
Repair and Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bumper Front Moulding	Broken	Replace	Replace
Bumper Front Grill	Broken	Replace	Replace
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Dented	Over 30mm	Repair and Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Qtr Panel nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Door nsr	Poor Previous Repair	Poor Paint	Refinish
Door nsf	Poor Previous Repair	Poor Paint	Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish

Vehicle Splat

The diagram shows a top-down view of a vehicle chassis. The components are labeled as follows:

- PP**: Power Plant, located in the front-left and front-right engine compartments.
- D1**: Drive Shaft, located on the left side of the chassis.
- D2**: Drive Shaft, located in the rear-left and rear-right engine compartments.
- C2**: Control Unit, located on the right side of the chassis.
- D3**: Drive Shaft, located on the right side of the chassis.
- S3**: Sensor, located on the right side of the chassis, near the rear.

Splat Key

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

PP
Poor Previous

Comments
<p>£65 ADDITIONAL FEE</p> <p>osr lamp broken</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>