

Vehicle Inspection Report

Date Inspected: 29/04/2025 17:07

Reg: OV14OXB

VIN: SALGA2JE7EA170237

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	LAND ROVER	Body Type	Estate	Doors	5
Model	RANGE ROVER VOGUE SE SDV8 - 4367cc	Fuel Type	Diesel	Colour	White
		Transmission	Auto	Year of MFR	2014
Mileage	52,696 miles			Date First Reg	07/05/2014

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	22/02/2026
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need	4
OSR Depth	6 mm	Refurb	
NSR Depth	6 mm	Tools	No
		Spare	Alloy

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service Yes
History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bonnet

Chipped
Multiple
Chips
Refinish

**Bumper
Front**

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



**Bumper
Front**

Chipped
Multiple
Chips
Smart
Repair


Wing osf

Scratched
Over
25mm Not

Thru Paint
Machine
Polish



Wing osf
Chipped
1 To 5
Smart
Repair



Screen Front
Chipped
UpTo
10mm
Smart
Repair

Door osf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door osf
Chipped
1 To 5
Smart
Repair

Door osr
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Qtr Panel osr

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Bumper Rear

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Bumper Rear

Chipped
Multiple
Chips
Smart
Repair



Boot Lid

Chipped
1 To 5
Smart
Repair

Qtr Panel nsr

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Door nsr

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door nsf

Chipped
1 To 5
Smart
Repair

Door nsf

Scratched
Over
25mm Not
Thru Paint
Machine
Polish




Door nsf

Chipped
1 To 5
Smart
Repair

Wing nsf

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Boot Lid	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish



Splat Key

C2
Multiple Chips

Comments
Last Service - 22/02/2025 at 52,677 miles (9 SERVICES (5 MAIN DEALER))
restricted performance on dash
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.