

Vehicle Inspection Report

Date Inspected: 29/04/2025 15:49

Inspected By: toby

Reg: GV16DWN

VIN: WDD1760122J470942

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	MERCEDES-BENZ	Body Type	Hatchback	Doors	5
Model	A 180 D SE EXECUTIVE - 1461cc	Fuel Type	Diesel	Colour	White
Mileage	116,590 miles	Transmission	Manual	Year of MFR	2016
		Gears	6	Date First Reg	31/05/2016

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	06/11/2025
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	No Spare

Interior Condition

Carpets	Poor
Upholstery	Average
Seats	Poor
Parcel Shelf	Yes
Odour	No

Service History

Service History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bonnet
Chipped
1 To 5
Smart
Repair



Bumper Front
Scratched
Over
100mm
Thru Paint
Refinish

Door osf
Scratched
Over

Wing osf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Screen Front

Chipped

UpTo 10mm

Smart Repair

25mm Not Thru Paint

Machine Polish



Door osf

Chipped

Edge Chip

Smart Repair

Door osr

Scratched

Over 25mm Not Thru Paint

Machine Polish



Door osr

Dented

2 Or Less UpTo 10mm

Smart Repair



Qtr Panel osr

Dented

Over 30mm

Repair and Refinish

Bumper Rear

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Rear

Chipped

Multiple Chips

Smart Repair

Qtr Panel nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish



Door nsr

Chipped

1 To 5

Smart Repair

Door nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish



Seat Base Cover osf

Torn

Over 3mm

Replace



Carpets Front

Torn


Over 10mm

Replace

Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	Edge Chip	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Seat Base Cover osf	Torn	Over 3mm	Replace
Carpets Front	Torn	Over 10mm	Replace

Vehicle Splat



Splat Key

- S3**
Scratch/Paint defect 100m +
- D1**
Dent/damage under 30mm
- D2**
Dent/damage 30-100mm
- C2**
Multiple Chips

Comments

£65 ADDITIONAL FEE Last Service - 01/06/2021 at 80,493 miles (1 SERVICE)

squeaky noise from engine

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.