

Vehicle Inspection Report

Date Inspected: 18/02/2025 09:55

Reg: WR63NBK

VIN: ZFA26300006123371

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	FIAT	Body Type	Van	Doors	6
Model	DOBLO 16V XL	Fuel Type	Diesel	Colour	Red
	MULTIJET LWB -	Transmission	Manual	Year of MFR	2013
	1598cc	Gears	6	Date First Reg	05/11/2013
Mileage	104,339 miles				

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	No
NSF Depth	5 mm	Tools	No
OSR Depth	4 mm	Spare	No Spare
NSR Depth	5 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No
Comments	seats stained

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	No	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	2	Parking Sensors	Rear
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment

Bonnet

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bonnet

Chipped

1 To 5

Smart
Repair

Bumper
Front

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper Front Moulding

Scuffed (Unpainted)

Over 100mm

Smart Repair



Wing osf

Dented

With Paint Damage

Repair and Refinish



Door osf

Dented

Over 30mm

Repair and Refinish



Door osr

Dented

Over 30mm

Repair and Refinish



Qtr Panel osr

Dented

Over 30mm

Repair and Refinish



Wing nsf

Dented

Over 30mm

Repair and Refinish



Door Mirror Assy nsf

Broken

Needs Replaced

Replace



Door nsf

Dented

Over 30mm

Repair and Refinish



Door nsr

Dented

Over 30mm

Repair and Refinish



Qtr Panel nsr

Dented

Over 30mm

Repair and Refinish



Bumper Rear Moulding

Scuffed (Unpainted)

Over 100mm

Smart Repair



Boot Lid

Dented

Over 30mm

Repair and Refinish

Roof

Dented

Over 30mm

Repair and Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Wing osf	Dented	With Paint Damage	Repair and Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Door nsf	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Bumper Rear Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Boot Lid	Dented	Over 30mm	Repair and Refinish
Roof	Dented	Over 30mm	Repair and Refinish

Vehicle Splat

FRONT

Splat Key

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

SC
Scuff

Comments
front bumper misaligned and noisy engine. rear door doesnt open
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.