

Vehicle Inspection Report

Date Inspected: 28/04/2025 14:35

Inspected By: toby

Reg: GD65GRK

VIN: WVVZZZ3CZGE091723

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	VOLKSWAGEN	Body Type	Estate	Doors	5
Model	PASSAT SE BUSINESS TDI BM - 1968cc	Fuel Type	Diesel	Colour	Grey
		Transmission	Auto	Year of MFR	2015
Mileage	171685 miles			Date First Reg	16/11/2015

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	14/04/2026
No. Keys	1

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	6 mm		
NSR Depth	6 mm	Tools Spare	Yes Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service History Stamps Yes

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment




Bonnet
Chipped
Over 5mm
Refinish



Bumper Front
Scratched

Over 100mm
Thru Paint
Refinish



Screen Front
Chipped

UpTo 10mm

Smart Repair

Door osf
Scratched

Door osf
Chipped



Wing osf
Chipped
1 To 5
Smart
Repair

Over
25mm Not
Thru Paint

Machine
Polish

1 To 5

Smart
Repair



Door osr
Chipped
1 To 5
Smart
Repair

Door osr
Scratched

Over
25mm Not
Thru Paint

Machine
Polish

**Qtr Panel
osr**
Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Qtr Panel
osr**
Chipped
1 To 5
Smart
Repair



**Bumper
Rear**
Dented

With Paint
Damage

Repair
and
Refinish



Boot Lid
Dented

Over
30mm

Repair
and
Refinish

**Qtr Panel
nsr**
Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door nsr
Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsr
Chipped
1 To 5
Smart
Repair

Door nsf
Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsf
Dented


Between
10mm +
30mm

Smart
Repair

Wing nsf
Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf
Chipped
1 To 5
Smart
Repair



**Door
Mirror
Assy nsf**
Broken

Needs
Replaced

Replace

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Over 5mm	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Bumper Rear	Dented	With Paint Damage	Repair and Refinish
Boot Lid	Dented	Over 30mm	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Dented	Between 10mm + 30mm	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Door Mirror Assy nsf	Broken	Replace	Replace

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D3
Dent/damage 100mm +

C2
Multiple Chips

Comments
<p>£100 ADDITIONAL FEE Last Service - 11/07/2023 at 141,659 miles (10 SERVICES (6 MAIN DEALER))</p> <p>noise while turning heater fan on.washer bottle cap broken</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>