

Vehicle Inspection Report

Date Inspected: 29/04/2025 17:16

Reg: LA23HKN

VIN: VR3USHNKKPJ625068

NAMA Grading



Grade

2

Appraised By: Eastbourne Car Auctions

General Details

Make	PEUGEOT	Body Type	Hatchback	Doors	5
Model	2008 ALLURE PREMIUM + PTE - 1199cc	Fuel Type	Petrol	Colour	Orange
Mileage	11,587 miles	Transmission	Manual	Year of MFR	2023
		Gears	6	Date First Reg	29/04/2023

Miscellaneous

V5 Location	Here
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition

Carpets
Upholstery
Seats
Parcel Shelf
Odour

Service History

Service No
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bumper Rear

Scratched
25 to
100mm
Thru Paint
Smart
Repair

Qtr Panel nsr

Scratched

Bumper Rear

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Door nsr

Scratched
Over

Boot Lid

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Over
25mm Not
Thru Paint
Machine
Polish

25mm Not
Thru Paint
Machine
Polish



Door nsr
Chipped
1 To 5
Smart
Repair

Door nsf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door nsf
Chipped
1 To 5
Smart
Repair

Qtr Panel nsr
Dented
2 Or Less
UpTo
10mm
Smart
Repair

Wing nsf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Screen Front
Chipped
UpTo
10mm
Smart
Repair



Bonnet
Chipped
1 To 5
Smart
Repair

Bumper Front
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Bumper Front
Chipped
Multiple
Chips
Smart
Repair

Wing osf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Wing osf
Chipped
1 To 5
Smart
Repair

Door osf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Door osf
Chipped
1 To 5
Smart
Repair

Door osr
Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Door osr
Dented
2 Or Less
UpTo
10mm
Smart
Repair




Qtr Panel osr
Chipped
1 To 5
Smart
Repair

Damage Lines

Component	Condition	Severity	Repair
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Dented	2 Or Less UpTo 10mm	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Chipped	1 To 5	Smart Repair

Vehicle Splat



Splat Key

- S2**
Scratch/Paint defect 30-100mm
- D1**
Dent/damage under 30mm
- C2**
Multiple Chips

Comments

£65 ADDITIONAL FEE

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.