



## **Vehicle Inspection Report**

Date Inspected: 19/02/2025 15:39

Reg: WJ21SKO

VSKCTND23U0157220 VIN:

NAMA Grading



Grade

Appraised By: Eastbourne Car Auctions

NISSAN Make

Model NAVARA TEKNA DCI AUTO - 2299cc

Mileage 132345 miles

**Fuel Type** 

**Transmission** 

Diesel Auto

**Doors** 

5

Average

Average

Average

No

No

Colour Bronze

Year of MFR 2021

**Date First Reg** 24/03/2021 Miscellaneous

**V5** Location

No. Keys

2

## Tyres & Wheels

**OSF Depth** 6 mm

NSF Depth 6 mm **OSR Depth** 

**NSR Depth** 5 mm

6 mm

Alloys

**Alloys That Need** Refurb

Tools

**Spare** No

Spare

Yes

1

No

Interior Condition

**Carpets** 

Upholstery

Seats

Parcel Shelf

Odour

Service History

Service No History

**Stamps** 

## Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

#### Damage Assessment

Door osf Chipped Edge Chip

> Smart Repair

Door nsr

Chipped

1 To 5

Smart

Repair

**Qtr Panel** osr

Scratched

UpTo 25mm Not Thru Paint

Machine Polish

Door nsf

Scratched

Wing nsf

Scratched

Door nsr

Chipped

Smart

Repair

Edge Chip

Over 25mm Not Thru Paint

Machine Polish

Over 25mm Not Thru Paint Machine



Bumper Front

Poor Previous Repair

Poor Paint

Refinish



**Bonnet** 

Chipped

1 To 5

Smart Repair



Screen Front

Polish


Chipped

UpTo 10mm

Smart Repair

## Damage Lines

Component Condition Severity Repair Door osf Chipped Edge Chip Smart Repair UpTo 25mm Not Thru Paint Qtr Panel osr Scratched Machine Polish Door nsr Chipped Edge Chip Smart Repair Chipped 1 To 5 Smart Repair Door nsr Door nsf Scratched Over 25mm Not Thru Paint Machine Polish Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish Bumper Front Poor Previous Repair Poor Paint Refinish Bonnet 1 To 5 Chipped Smart Repair Screen Front Chipped UpTo 10mm Smart Repair



# Comments

# £100 ADDITIONAL FEE

4wd system fault

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.