

### Vehicle Inspection Report

Date Inspected: 05/03/2025 16:04

**Reg:** HK17VVS

**VIN:** VF1RFB00056222557

### NAMA Grading



Grade

**3**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	RENAULT	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	MEGANE GT LINE NAV DCI - 1598cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Black
<b>Mileage</b>	67,225 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2017
		<b>Gears</b>	6	<b>Date First Reg</b>	22/06/2017

### Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	21/12/2025
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	5 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	5 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	5 mm	<b>Tools</b>	No
<b>NSR Depth</b>	5 mm	<b>Spare</b>	Space Saver

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Poor
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No
<b>Comments</b>	seats heavily stained

### Service History

<b>Service History</b>	Yes
<b>Stamps</b>	


### Extras

<b>Metallic Paint</b>	No	<b>Central Locking</b>	Yes	<b>Interior</b>	Half Leather	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No



**Bonnet**

Chipped  
1 To 5  
Smart  
Repair



**Bumper  
Front**

Scratched  
  
25 to  
100mm  
Thru Paint  
  
Smart  
Repair

**Bumper  
Front**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Wing osf**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Door osf**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Door osr**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Qtr Panel  
osr**

Chipped  
  
Over 5mm  
Refinish

**Bumper  
Rear**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Bumper  
Rear**

Scratched  
  
25 to  
100mm  
Thru Paint  
  
Smart  
Repair

**Boot Lid**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Qtr Panel  
nsr**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Qtr Panel  
nsr**

Chipped  
  
1 To 5  
  
Smart  
Repair

**Door nsr**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish

**Door nsf**

Scratched  
  
Over  
25mm Not  
Thru Paint  
  
Machine  
Polish



**Wing nsf**

Dented  
  
With Paint  
Damage  
  
Repair  
and  
Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	Over 5mm	Refinish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Dented	With Paint Damage	Repair and Refinish

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

Comments
<p>Last Service - 13/03/2019 at 21,407 miles (1 SERVICE)</p> <p>front bumper misaligned</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>