

Vehicle Inspection Report

Date Inspected: 23/04/2025 16:55

Reg: EN19MWW

VIN: W0VZT6EB6K1067720

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	VAUXHALL	Body Type	Hatchback	Doors	5
Model	INSIGNIA TECH LINE NAV TU - 1490cc	Fuel Type	Petrol	Colour	Blue
Mileage	83930 miles	Transmission	Manual	Year of MFR	2019
		Gears	6	Date First Reg	31/05/2019

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	2
OSR Depth	5 mm	Tools	Yes
NSR Depth	5 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Wing osf

Chipped
1 To 5
Smart
Repair



Door osf

Chipped
1 To 5
Smart
Repair



Door osf

Chipped
Edge Chip
Smart
Repair



Door osf






Dented
Between
10mm +
30mm
Smart

Door osr

Chipped
1 To 5
Smart
Repair

Door osr

Dented
2 Or Less
UpTo
10mm
Smart

	Repair		Repair
	Qtr Panel osr Dented Between 10mm + 30mm Smart Repair		Qtr Panel osr Chipped 1 To 5 Smart Repair
	Bumper Rear Scratched Over 25mm Not Thru Paint Machine Polish		Bumper Rear Chipped 1 To 5 Smart Repair
	Qtr Panel nsr Scratched Over 25mm Not Thru Paint Machine Polish		Door nsr Scratched Over 25mm Not Thru Paint Machine Polish
	Door nsf Scratched Over 25mm Not Thru Paint Machine Polish		Door nsr Scratched UpTo 25mm Thru Paint Smart Repair
			Screen Front Chipped UpTo 10mm Smart Repair
	Door Mirror Assy osf Scratched (Painted) UpTo 25mm Thru Paint Smart Repair		Bumper Front Poor Previous Repair Poor Paint Refinish
			Bonnet Poor Previous Repair Poor Paint Refinish

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Chipped	1 To 5	Smart Repair
Door osf	Chipped	Edge Chip	Smart Repair
Door osf	Dented	Between 10mm + 30mm	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Dented	Between 10mm + 30mm	Smart Repair
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	1 To 5	Smart Repair
Tailgate	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door Mirror Assy osf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Bumper Front	Poor Previous Repair	Poor Paint	Refinish
Bonnet	Poor Previous Repair	Poor Paint	Refinish

Vehicle Splat

Splat Key

S1
Scratch/Paint defect to 30mm

D1
Dent/damage under 30mm

C2
Multiple Chips

PP
Poor Previous

Comments
<p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>