

Vehicle Inspection Report

Date Inspected: 11/03/2025 09:05

Reg: YD610EA

VIN: WMWZM32060T130399

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	MINI	Body Type	Convertible	Doors	2
Model	ONE - 1598cc	Fuel Type	Petrol	Colour	White
Mileage	108,164 miles	Transmission	Manual	Year of MFR	2011
		Gears	6	Date First Reg	12/10/2011

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	07/06/2025
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need	4
OSR Depth	6 mm	Refurb	
NSR Depth	6 mm	Tools	No
		Spare	No Spare

Interior Condition







Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service Yes
History
Stamps


Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	4	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment			
	Door osf Chipped 1 To 5 Smart Repair	Door osf Scratched Over 25mm Not Thru Paint Machine Polish	Qtr Panel osr Scratched Over 25mm Not Thru Paint Machine Polish
	Qtr Panel osr Chipped 1 To 5 Smart Repair	 Bumper Rear Poor Previous Repair Paint Flake Refinish	 Bonnet Chipped 1 To 5 Smart Repair
	Screen Front Chipped Over 10mm Replace	 Door Pad osf Scuffed UpTo 25mm Smart Repair	

Damage Lines			
Component	Condition	Severity	Repair
Door osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Bumper Rear	Poor Previous Repair	Paint Flake	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	Over 10mm	Replace
Door Pad osf	Scuffed	UpTo 25mm	Smart Repair

Vehicle Splat



Splat Key

C2

Multiple Chips

PP

Poor Previous

X

Req Replacement

Comments

Last Service - 18/02/2016 at 30,566 miles (5 main dealer services)

convertible roof not working,,high clutch

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.