

Vehicle Inspection Report

Date Inspected: 27/03/2025 15:54

Reg: EK61ZCT

VIN: WAUZZZ8P5CA049550

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	AUDI	Body Type	Hatchback	Doors	5
Model	A3 TDI - 1598cc	Fuel Type	Diesel	Colour	Black
Mileage	114253 miles	Transmission	Manual	Year of MFR	2011
		Gears	5	Date First Reg	13/10/2011

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need Refurb	4
OSR Depth	6 mm	Tools	No
NSR Depth	6 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Wing osf

Poor
Previous
Repair

Poor Paint
Refinish



Door osf

Poor
Previous
Repair

Poor Paint
Refinish

Door osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Door osr







Dented

2 Or Less
UpTo
10mm

Bumper
Rear

Scratched

Over
25mm Not

	Smart Repair		Qtr Panel osr Poor Previous Repair Paint Flake Refinish	Thru Paint Machine Polish
	Bumper Rear Chipped Multiple Chips Smart Repair		Tailgate Scratched Over 25mm Not Thru Paint Machine Polish	Qtr Panel nsr Scratched Over 25mm Not Thru Paint Machine Polish
	Door nsr Scratched Over 25mm Not Thru Paint Machine Polish		Door nsr Chipped Edge Chip Smart Repair	Door nsf Scratched Over 25mm Not Thru Paint Machine Polish
	Door Mirror Assy nsf Scratched (Painted) Over 25mm Not Thru Paint Machine Polish		Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish	 Bumper Front Poor Previous Repair Poor Paint Refinish
	Bonnet Scratched Over 25mm Not Thru Paint Machine Polish		Screen Front Chipped UpTo 10mm Smart Repair	 Roof Chipped 1 To 5 Smart Repair
	Tailgate Dented 2 Or Less UpTo 10mm Smart Repair			

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Poor Previous Repair	Poor Paint	Refinish
Door osf	Poor Previous Repair	Poor Paint	Refinish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel osr	Poor Previous Repair	Paint Flake	Refinish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Chipped	Multiple Chips	Smart Repair
Tailgate	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	Edge Chip	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Poor Previous Repair	Poor Paint	Refinish
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Roof	Chipped	1 To 5	Smart Repair
Tailgate	Dented	2 Or Less UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

D1
Dent/damage under 30mm

C2
Multiple Chips

PP
Poor Previous

Comments
<p>£65 ADDITIONAL FEE</p> <p>missing buttons on 1 key,ignition barrel fault,airbag light on,parking sensors don't work,rear trim on osf seat broken</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>