

### Vehicle Inspection Report

Date Inspected: 29/04/2025 16:54

**Reg:** MV68CTK

**VIN:** WBA6S32000VD38259

### NAMA Grading



Grade

**3**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	BMW	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	220i SE AUTO - 1998cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	Silver
<b>Mileage</b>	36,267 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2018
				<b>Date First Reg</b>	31/10/2018

### Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	21/09/2025
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	5 mm	<b>Tools</b>	No
<b>NSR Depth</b>	5 mm	<b>Spare</b>	Inflation Kit

### Interior Condition










<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No

### Service History

**Service History**  
Stamps

### Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Cloth	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

	<p><b>Bumper Front</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>		<p><b>Bumper Front</b></p> <p>Chipped</p> <p>Multiple Chips</p> <p>Smart Repair</p>		<p><b>Bonnet</b></p> <p>Chipped</p> <p>1 To 5</p> <p>Smart Repair</p>
	<p><b>Screen Front</b></p> <p>Chipped</p> <p>UpTo 10mm</p> <p>Smart Repair</p>		<p><b>Door osf</b></p> <p>Chipped</p> <p>1 To 5</p> <p>Smart Repair</p>		<p><b>Door osr</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>
	<p><b>Door osr</b></p> <p>Chipped</p> <p>1 To 5</p> <p>Smart Repair</p>		<p><b>Qtr Panel osr</b></p> <p>Dented</p> <p>Over 30mm</p> <p>Repair and Refinish</p>		<p><b>Bumper Rear</b></p> <p>Poor Previous Repair</p> <p>Poor Paint Refinish</p>
	<p><b>Qtr Panel nsr</b></p> <p>Dented</p> <p>Over 30mm</p> <p>Repair and Refinish</p>		<p><b>Door nsr</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>		<p><b>Door nsf</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>
	<p><b>Wing nsf</b></p> <p>Scratched</p> <p>Over 25mm Not Thru Paint</p> <p>Machine Polish</p>				

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Qtr Panel nsr	Dented	Over 30mm	Repair and Refinish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

FRONT

Splat Key

**D2**  
Dent/damage 30-100mm

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments
Last Service - 05/03/2025 at 36,022 miles (5 SERVICES (4 MAIN DEALER))
.
No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.