

Vehicle Inspection Report

Date Inspected: 18/02/2025 12:39

Reg: GV19OAP

VIN: VF7SXHMRPKT542689

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	CITROEN	Body Type	Hatchback	Doors	5
Model	C3 ORIGINS PURETECH S/S - 1199cc	Fuel Type	Petrol	Colour	Grey
		Transmission	Manual	Year of MFR	2019
Mileage	38,977 miles	Gears	5	Date First Reg	30/04/2019

Miscellaneous

V5 Location	Here
No. Keys	1

Tyres & Wheels

OSF Depth	6 mm	Alloys	Yes
NSF Depth	6 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	Steel

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Boot Lid

Dented

Over
30mm

Repair
and
Refinish



Bumper
Rear

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Bumper
Rear

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Qtr Panel
nsr

Scratched

Over

Door nsr

Scratched

Over
25mm Not

25mm Not
Thru Paint

Machine
Polish

Thru Paint

Machine
Polish



Door nsr

Chipped

1 To 5

Smart
Repair

Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door nsf

Chipped

1 To 5

Smart
Repair

**Door
Mirror
Assy nsf**

Scratched
(Painted)

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf

Dented

Over
30mm

Repair
and
Refinish



**Bumper
Front**

Chipped

Multiple
Chips

Smart
Repair

**Bumper
Front**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bonnet

Chipped

1 To 5

Smart
Repair

Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

**Door
Mirror
Assy osf**

Scratched
(Painted)

Over
25mm Not
Thru Paint

Machine
Polish

Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osf

Chipped

1 To 5


Smart
Repair

Door osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osr


Chipped

1 To 5

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Boot Lid	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Dented	Over 30mm	Repair and Refinish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy osf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair

Vehicle Splat



Splat Key

S2
Scratch/Paint defect 30-100mm

D2
Dent/damage 30-100mm

C2
Multiple Chips

Comments
£65 ADDITIONAL FEE, MOT mileage discrepancy EXPIRED MOT. Last Service - 09/11/2023 at 31,400 miles light on dash No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.