

Vehicle Inspection Report

Date Inspected: 17/03/2025 17:27

Reg: EJ70HTV

VIN: JTDKGNEC00N577862

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	TOYOTA	Body Type	Hatchback	Doors	5
Model	AYGO X-PLAY TSS	Fuel Type	Petrol	Colour	Red
	VVT-I CVT - 998cc	Transmission	Auto	Year of MFR	2020
Mileage	12,364 miles			Date First Reg	30/11/2020

Miscellaneous

V5 Location	Here
No. Keys	1

Tyres & Wheels

OSF Depth	5 mm	Alloys	No
NSF Depth	5 mm	Tools	No
OSR Depth	5 mm	Spare	No Spare
NSR Depth	5 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	No
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bonnet

Chipped
1 To 5
Smart
Repair



Bumper
Front

Scratched
25 to
100mm
Thru Paint
Smart
Repair

Wing osf

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Door osr

Scratched
Over
25mm Not

Qtr Panel
nsr

Scratched
Over

Thru Paint
Machine
Polish



**Qtr Panel
osr**
Chipped
Edge Chip
Smart
Repair

25mm Not
Thru Paint
Machine
Polish

Door nsr
Scratched
Over
25mm Not
Thru Paint
Machine
Polish




Door nsf
Chipped
1 To 5
Smart
Repair

Door nsf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Wing nsf
Scratched
Over
25mm Not
Thru Paint
Machine
Polish

**Door
Mirror
Assy osf**
Scratched
(Painted)
Over
25mm Not
Thru Paint
Machine
Polish



**Bumper
Rear**
Poor
Previous
Repair
Poor Paint
Refinish




Door nsr
Chipped
1 To 5
Smart
Repair



Door osf
Poor
Previous
Repair
Poor Paint
Refinish




**Seat
Base
Cover
osr**
Scuffed
UpTo
25mm
Smart
Repair



**Seat
Base
Cover
nsr**
Scuffed
UpTo
25mm
Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	Edge Chip	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy osf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Door nsr	Chipped	1 To 5	Smart Repair
Door osf	Poor Previous Repair	Poor Paint	Refinish
Seat Base Cover osr	Scuffed	UpTo 25mm	Smart Repair
Seat Base Cover nsr	Scuffed	UpTo 25mm	Smart Repair

Vehicle Splat



Splat Key

S2
Scratch/Paint defect 30-100mm

C1
Single Chip

C2
Multiple Chips

PP
Poor Previous

Comments

£100 Additional Fee. EXPIRED MOT. Signs of front end accident damage.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.