

Vehicle Inspection Report

Date Inspected: 11/03/2025 12:35

Reg: MK67MJE

VIN: WF0SXXWPGSHA53340

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	FORD	Body Type	Van	Doors	5
Model	TRANSIT CONNECT 240 TREND - 1499cc	Fuel Type	Diesel	Colour	White
Mileage	92,666 miles	Transmission	Manual	Year of MFR	2017
		Gears	5	Date First Reg	29/09/2017

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	6 mm	Alloys	No
NSF Depth	6 mm	Tools	No
OSR Depth	6 mm	Spare	No Spare
NSR Depth	6 mm		

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	3	Parking Sensors	No
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Bonnet

Chipped

1 To 5

Smart
Repair



Bumper Front

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Bumper Front

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf

Chipped

1 To 5

Smart
Repair



Door nsf

Chipped

1 To 5

Smart
Repair



Door nsr

Chipped

Multiple
Chips

Refinish



Qtr Panel nsr

Chipped

Multiple
Chips

Refinish



Boot Lid

Scratched

Over
25mm
Thru Paint

Refinish



Bumper Rear Moulding

Scuffed
(Unpainted)

Over
100mm

Smart
Repair



Qtr Panel osr

Scratched

Over
25mm
Thru Paint

Refinish



Door osf

Dented

Over
30mm

Repair
and
Refinish



Wing osf

Chipped


1 To 5

Smart
Repair

Damage Lines

Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Chipped	1 To 5	Smart Repair
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Chipped	Multiple Chips	Refinish
Qtr Panel nsr	Chipped	Multiple Chips	Refinish
Boot Lid	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear Moulding	Scuffed (Unpainted)	Over 100mm	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Dented	Over 30mm	Repair and Refinish
Wing osf	Chipped	1 To 5	Smart Repair

Vehicle Splat



Splat Key

S2

Scratch/Paint defect 30-100mm

S3

Scratch/Paint defect 100mm +

D3

Dent/damage 100mm +

C2

Multiple Chips

SC

Scuff

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.