



VEHICLE INSPECTION REPORT

SL14OXU

Kia Sportage 1.6 GDi ISG 2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/05/2014	Keys	2	CAP Clean	£1,500.00
Year	2014	Service history	Yes	CAP Average	£1,125.00
Mileage	73,397 Miles Warranted	Service documents	Printout	CAP Below	£890.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	SILVER	Last service date	21/05/2025	Gears	6
VIN	U5YPC814LEL465856	Last service miles	72,162		
Body Style	Estate	MOT Due	24/05/2026		

Last Service - 21.05.2025 at 72162 miles (2 services) Roof will not open
Oil warning light is on
Rear electric windows faulty

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	NEXEN	2.0mm
OSR	NEXEN	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage




7: Qtr Panel nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Boot Lid
Poor Previous Repair
Poor Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Up To 50mm




14: Door osr
Dented
With Paint Damage



15: Door osf
Chipped
Multiple Chips



16: Wing osf
Chipped
1 To 5



17: Wing osf
Scratched
Over 25mm Not Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	Fault	Steering	OK