



VEHICLE INSPECTION REPORT

MK59ABF

Mini Convertible 1.6 Cooper S 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	08/09/2009	Keys	2	CAP Clean	£1,400.00
Year	2009	Service history	Yes	CAP Average	£1,000.00
Mileage	79,544 Miles Warranted	Service documents	Service Book	CAP Below	£625.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	BLACK	Last service date	24/06/2024	Gears	6
VIN	WMWMS32060TX91978	Last service miles	71,337		
Body Style	Convertible	MOT Due	24/06/2026		

£65 ADDITIONAL FEE.

Last Service - 24.06.2024 at 71337 miles (7 services)

Boot doesn't open and starting fault.

Rough idle

Tyres

NSF	BUDGET	3.0mm
NSR	SUNNY	2.0mm
OSF	PIRELLI	2.0mm
OSR	YOKOHAMA	2.0mm
Spare		

Features


- Cruise control
- Electric door mirrors
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Telephone
- Electric sunroof
- Front electric windows
- Drivers airbag
- Central locking
- Radio/CD
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Body coloured bumpers
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Poor Previous Repair
Poor Paint



6: Qtr Panel nsr
Chipped
1 To 5

No Image




7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

8: Wheel nsr
Scratched
Up To 50mm



9: Bumper Rear
Chipped
Multiple Chips




10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Boot Lid
Poor Previous Repair
Poor Paint



12: Qtr Panel osr
Chipped
1 To 5



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Up To 50mm




15: Door osf
Dented
With Paint Damage



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm



18: Bumper Front Grill
Broken
Replace



19: A Post os
Dented
Over 30mm



20: A Post ns
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK