



VEHICLE INSPECTION REPORT

AF59TMX

Toyota Avensis 2.0 D-4D T4 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/12/2009	Keys	2	CAP Clean	£930.00
Year	2009	Service history	Yes	CAP Average	£530.00
Mileage	151,851 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	18	Gearbox	MANUAL
Colour	BLUE	Last service date	28/10/2024	Gears	6
VIN	SB1ED76LX0E028478	Last service miles	147,755		
Body Style	Estate	MOT Due	05/11/2025		

Last service 28/10/2024 at 147,755 miles- 18 services (8 main dealer) Engine rattling

Tyres

NSF
NSR
OSF
OSR
Spare

Features


- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- PAS
- Radio/CD
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Fogdriving Lamp osf
Broken
Replace



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Wing nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsf
Dented
Over 30mm



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Qtr Panel osr
Dented
Over 30mm



14: Wheel osr
Scratched
Up To 50mm



15: Door osr
Dented
Over 30mm



16: Door nsf
Scratched
Over 25mm Thru Paint



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK