

### Vehicle Inspection Report

Date Inspected: 11/03/2025 12:55

**Reg:** GL09RXB

**VIN:** JTNML11000J039657

### NAMA Grading



Grade

**4**

Appraised By: Eastbourne Car Auctions

### General Details

<b>Make</b>	TOYOTA	<b>Body Type</b>	Hatchback	<b>Doors</b>	3
<b>Model</b>	IQ2 VVT-I - 998cc	<b>Fuel Type</b>	Petrol	<b>Colour</b>	White
<b>Mileage</b>	86411 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2009
		<b>Gears</b>	5	<b>Date First Reg</b>	11/08/2009

### Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

### Tyres & Wheels

<b>OSF Depth</b>	6 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	6 mm	<b>Alloys That Need Refurb</b>	3
<b>OSR Depth</b>	7 mm	<b>Tools</b>	No
<b>NSR Depth</b>	7 mm	<b>Spare</b>	No Spare

### Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	No
<b>Odour</b>	No

### Service History

**Service No History Stamps**

### Extras

<b>Metallic Paint</b>	No	<b>Central Locking</b>	Yes	<b>Interior</b>	Leather	<b>Electric Seats</b>	No
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	2	<b>Heated Seats</b>	No
<b>Stereo</b>	Radio	<b>Sat Nav</b>	No	<b>Cruise</b>	No	<b>Xenons</b>	No
<b>Keyless Entry</b>	Yes	<b>Towbar</b>	No	<b>Number of Seats</b>	4	<b>Parking Sensors</b>	No
<b>Phone Kit</b>	No	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No



**Seat Back Cover osf**

Scuffed  
Over 25mm  
Smart Repair



**Bumper Front**

Scratched  
Over 100mm  
Thru Paint  
Refinish



**Bonnet**

Chipped  
1 To 5  
Smart Repair



**Wing osf**

Chipped  
1 To 5  
Smart Repair

**Door Mirror Assy osf**

Scratched (Painted)  
Over 25mm Not Thru Paint  
Machine Polish



**Door osf**

Dented  
Over 30mm  
Repair and Refinish



**Roof**

Poor Previous Repair  
Paint Flake  
Refinish



**Qtr Panel osr**

Chipped  
Multiple Chips  
Refinish



**Bumper Rear**

Scratched  
Over 100mm Thru Paint  
Refinish



**Boot Lid**

Chipped  
1 To 5  
Smart Repair



**Qtr Panel nsr**

Chipped  
1 To 5  
Smart Repair



**Door nsf**

Chipped  
Multiple Chips  
Refinish



**Door Mirror Assy nsf**

Broken  
Needs Replaced  
Replace

**Wing nsf**

Scratched  
Over 25mm Not Thru Paint  
Machine Polish

Damage Lines			
Component	Condition	Severity	Repair
Seat Back Cover osf	Scuffed	Over 25mm	Smart Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door Mirror Assy osf	Scratched (Painted)	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	Over 30mm	Repair and Refinish
Roof	Poor Previous Repair	Paint Flake	Refinish
Qtr Panel osr	Chipped	Multiple Chips	Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsf	Chipped	Multiple Chips	Refinish
Door Mirror Assy nsf	Broken	Replace	Replace
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments
<p>engine noisy and exhaust blowing</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>