

Vehicle Inspection Report

Date Inspected: 24/04/2025 13:04

Reg: LR17LPP

VIN: AHTHB3CD402119318

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	TOYOTA	Fuel Type	Diesel	Doors	4
Model	HILUX ICON D-4D	Transmission	Manual	Colour	Grey
	4WD DCB - 2393cc	Gears	6	Year of MFR	2017
Mileage	124646 miles			Date First Reg	16/03/2017

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	7 mm	Alloys	Yes
NSF Depth	7 mm	Tools	No
OSR Depth	7 mm	Spare	No Spare
NSR Depth	7 mm		

Interior Condition


Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No
Comments	SEATS STAINED

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	Yes	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No



Wing osf

Chipped
1 To 5
Smart
Repair




Door osf

Dented
Over
30mm
Repair
and
Refinish




Door osr

Dented
Over 2
UpTo
10mm
Smart
Repair



Door osr

Chipped
1 To 5
Smart
Repair




Qtr Panel osr

Chipped
1 To 5
Smart
Repair



Tailgate

Dented
With Paint
Damage
Repair
and
Refinish



Qtr Panel nsr

Dented
With Paint
Damage
Repair
and
Refinish

Door nsr

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Door nsf

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Wing nsf

Scratched
Over
25mm Not
Thru Paint
Machine
Polish

Bumper Front

Scratched
Over
25mm Not
Thru Paint
Machine
Polish



Bonnet

Chipped
Multiple
Chips
Refinish

Screen Front

Chipped
UpTo
10mm
Smart
Repair



Roof

Scratched
Over
25mm
Thru Paint
Refinish

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 2 UpTo 10mm	Smart Repair
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Tailgate	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bonnet	Chipped	Multiple Chips	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Roof	Scratched	Over 25mm Thru Paint	Refinish

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.