

Vehicle Inspection Report

Date Inspected: 02/04/2025 16:22

Reg: AJ09UKD

VIN: WBAUH52070E340072

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	BMW	Body Type	Hatchback	Doors	5
Model	116D SPORT - 1995cc	Fuel Type	Diesel	Colour	Black
Mileage	140,796 miles	Transmission	Manual	Year of MFR	2009
		Gears	6	Date First Reg	30/04/2009

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	21/05/2025
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No
Comments	stereo button missing

Service History

Service History	Yes
Stamps	

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	No	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No



Bumper Rear
Poor Previous Repair
Poor Paint Refinish

Boot Lid
Scratched
Over 25mm Not Thru Paint
Machine Polish



Qtr Panel osr
Dented
With Paint Damage
Repair and Refinish



Door osr
Scratched
Over 25mm Thru Paint Refinish



Door osf
Chipped
Multiple Chips Refinish



Wing osf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Screen Front
Chipped
UpTo 10mm
Smart Repair



Bonnet
Chipped
Multiple Chips Refinish



Bumper Front
Poor Previous Repair
Paint Flake Refinish



Wing nsf
Dented
Over 30mm
Repair and Refinish



Door nsf
Dented
Over 30% Of Panel
Replace



Door nsr
Dented
Over 30% Of Panel
Replace



Qtr Panel nsr
Dented
With Paint Damage
Repair and Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Poor Previous Repair	Poor Paint	Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Dented	With Paint Damage	Repair and Refinish
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Chipped	Multiple Chips	Refinish
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Poor Previous Repair	Paint Flake	Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish
Door nsf	Dented	Over 30% Of Panel	Replace
Door nsr	Dented	Over 30% Of Panel	Replace
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish

Vehicle Splat

Splat Key

S3
Scratch/Paint defect 100m +

D3
Dent/damage 100mm +

C2
Multiple Chips

PP
Poor Previous

X
Req Replacement

Comments
<p>£65 ADDITIONAL FEE. Last Service - 16/01/2025 at 140,009 miles (11 services (2 main dealer))</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>