

Vehicle Inspection Report

Date Inspected: 14/03/2025 13:13

 Reg:
 GL70LWW

 VIN:
 6FPPXXMJ2PLY37059



Appraised By: Eastbourne Car Auctions

General Details							Miscellaneous	
	I RANGER WILDTRAK ECOBLUE 4 - 1996cc		4x Di i on Au	esel Colour	4 Grey 2020 18/12/20		V5 Location MOT Locatior MOT Expiry No. Keys	Here Here 17/12/2025 2
Tyres & Wheels				Interior Cond	ition		Service History	
OSF Depth6 mmNSF Depth6 mmOSR Depth6 mmNSR Depth6 mm		AlloysYesToolsNoSpareNo Spare		Carpets Upholstery Seats Parcel Shelf Odour	Average		Service Yes History Stamps	
Extras								
Metallic Paint	Yes	Central Locking	g Yes	Interior	Leather	Electric Sea	its Yes	6
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seat	ts Yes	3
Stereo	Radio	Sat Nav	Built Ir	Cruise	Yes	Xenons	No	
		Towbar	Yes	Number of Seats	5	Parking Sen	isors Fro	ont & Rear
Keyless Entry	Yes	Towbar	163	Humber of Ocuto	0	i annig een		ant of i total

Damage Assessment







Bumper Front Cracked UpTo

Wing osf

Chipped

1 To 5

Smart

Repair

Door osf

Chipped

Smart

Repair

Edge Chip

Qtr Panel

Scratched

25mm Not

Thru Paint

Machine

Polish

osr

Over

Repair and Refinish

Condition

Chipped

Scratched

Scratched

Scratched

Scratched Chipped

Scratched

Cracked

Dented

Chipped

Chipped

Chipped

25mm

Wing osf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door osr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Tailgate



Door osf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Door osr

Chipped Edge Chip Smart

Repair



Bonnet Dented With Paint Damage Repair and Refinish

Chipped 1 To 5 Smart Repair

25mm Not Thru Paint Machine Polish

Door nsr

Scratched

Over

Screen Front Chipped UpTo 10mm

Smart Repair

Damage Lines


Component						
Wing osf						
Wing osf						
Door osf						
Door osf						
Door osr						
Door osr						
Qtr Panel osr						
Tailgate						
Door nsr						
Bumper Front						
Bonnet						
Screen Front						

Severity

1 To 5 Over 25mm Not Thru Paint Over 25mm Not Thru Paint Edge Chip Over 25mm Not Thru Paint Edge Chip Over 25mm Not Thru Paint 1 To 5 Over 25mm Not Thru Paint UpTo 25mm With Paint Damage UpTo 10mm

Repair

Smart Repair Machine Polish Machine Polish Smart Repair Machine Polish Smart Repair Machine Polish Smart Repair Machine Polish Repair and Refinish Repair and Refinish Smart Repair



Comments

£100 ADDITIONAL FEE. Last Service - 19/09/2024 at 97,954 miles (3 MAIN DEALER SERVICES)

dpf light on, front bumper out of line

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.