

Vehicle Inspection Report

Date Inspected: 18/03/2025 11:12

Reg: LL65BZX

VIN: JN1TDAT32U0001083

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

Make	NISSAN	Body Type	Estate	Doors	5
Model	X-TRAIL N-TEC DIG-T - 1618cc	Fuel Type	Petrol	Colour	Green
Mileage	102,706 miles	Transmission	Manual	Year of MFR	2015
		Gears	6	Date First Reg	23/11/2015

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No
Comments	seats heavily worn

Service History

Service No History Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	Yes



Bumper Rear
Scratched
Over 100mm Thru Paint
Refinish



Door nsf
Scratched
Over 25mm Thru Paint
Refinish



Wing osf
Dented
Over 30mm
Repair and Refinish



Door osr
Dented
Over 30mm
Repair and Refinish



Qtr Panel nsr
Dented
With Paint Damage
Repair and Refinish



Boot Lid
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door nsr
Dented
With Paint Damage
Repair and Refinish



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Door osf
Dented
Over 30mm
Repair and Refinish

Bonnet
Chipped
1 To 5
Smart Repair

Qtr Panel osr
Dented
Over 30mm
Repair and Refinish

Roof
Scratched
Over 25mm Not Thru Paint
Machine Polish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Scratched	Over 25mm Thru Paint	Refinish
Wing nsf	Scratched	Over 25mm Thru Paint	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing osf	Dented	Over 30mm	Repair and Refinish
Bonnet	Chipped	1 To 5	Smart Repair
Door osf	Dented	Over 30mm	Repair and Refinish
Door osr	Dented	Over 30mm	Repair and Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Roof	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish

Vehicle Splat

A top-down schematic of a vehicle, likely a car, with various components labeled in red text. The labels are as follows:

- D2**: Located on the left side of the vehicle, near the front wheel.
- D3**: Located on the left side of the vehicle, near the rear wheel.
- S3**: Located on the left side of the vehicle, near the front wheel.
- S3**: Located on the left side of the vehicle, near the rear wheel.
- C2**: Located on the right side of the vehicle, near the front wheel.
- S3**: Located on the right side of the vehicle, near the front wheel.
- S3**: Located on the right side of the vehicle, near the rear wheel.
- D3**: Located on the right side of the vehicle, near the rear wheel.

Splat Key

S3	Scratch/Paint defect 100m +
D2	Dent/damage 30-100mm
D3	Dent/damage 100mm +
C2	Multiple Chips

Comments

eml on

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.