

## VEHICLE INSPECTION REPORT

LL64LNM

### Porsche Panamera 3.0 [300] V6 Diesel 4dr Tiptronic S

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	TBC

nama  
GRADE 3

#### Details

Reg. date	20/11/2014
Year	2014
Mileage	85,755 Miles Warranted
Fuel Type	DIESEL
Colour	GREY

VIN	CAP Average	£10,850.00
Body Style	CAP Below	£9,800.00
Keys	Gearbox	AUTOMATIC
MOT Due	Gears	8
CAP Clean	Doors	5

£65 ADDITIONAL FEE

#### Tyres

NSF	MICHELIN	2.0mm
NSR	HANKOOK	4.0mm
OSF	MICHELIN	4.0mm
OSR	HANKOOK	4.0mm
Spare		

## Features


• Bluetooth connection	• Cruise control	• Front parking sensor	• Heated front seat
• PAS	• Rear parking sensor	• Steering wheel mounted controls	• Audio remote control
• Radio/CD	• Body coloured bumpers	• Electric door mirrors	• Electric sunroof
• Opening panoramic glass roof	• Air conditioning	• Climate control	• Electrically adjustable drivers seat
• Electrically adjustable passenger seat	• Front armrest	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear electric windows	• Rear headrests	• Metallic Paint
• ABS	• Curtain airbags	• Drivers airbag	• Passenger airbag
• Side airbags	• Traction control	• Central locking	• Remote central locking
• Leather seat trim	• Alloy wheels		

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

# No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Dented  
2 Or Less UpTo 10mm



6: Door nsf  
Poor Previous Repair  
Poor Paint



7: Door nsr  
Chipped  
1 To 5


8: Wheel nsr  
Scratched  
Up To 50mm



9: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



10: Bumper Rear  
Chipped  
Multiple Chips



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



13: Wheel osr  
Scratched  
Up To 50mm



14: Door osr  
Poor Previous Repair  
Poor Paint



15: Door osf  
Chipped  
1 To 5

No Image

16: Door osf  
Scratched  
Over 25mm Not Thru Paint



17: Wing osf  
Chipped  
1 To 5



18: Wheel osf  
Scratched  
Up To 50mm

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		