

Vehicle Inspection Report

Date Inspected: 23/04/2025 17:11

Reg: LG69JRZ

VIN: WF0EXXWPCEKJ42840

NAMA Grading



Grade

5

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	FORD	<b>Body Type</b>	Hatchback	<b>Doors</b>	5
<b>Model</b>	MONDEO TITANIUM EDITION E - 1995cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Black
<b>Mileage</b>	70509 miles	<b>Transmission</b>	Manual	<b>Year of MFR</b>	2019
		<b>Gears</b>	6	<b>Date First Reg</b>	26/11/2019

Miscellaneous

<b>V5 Location</b>	
<b>No. Keys</b>	2

Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	5 mm	<b>Tools</b>	No
<b>NSR Depth</b>	4 mm	<b>Spare</b>	Inflation Kit

Interior Condition

<b>Carpets</b>	Average
<b>Upholstery</b>	Average
<b>Seats</b>	Average
<b>Parcel Shelf</b>	Yes
<b>Odour</b>	No


Service History

**Service No History Stamps**

Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Leather	<b>Electric Seats</b>	Yes
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	Yes
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	Yes	<b>Towbar</b>	No	<b>Number of Seats</b>	5	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	No	<b>EML</b>	No

Damage Assessment



Bonnet

Chipped  
Multiple Chips  
Refinish



Bumper Front

Scratched  
Over 100mm Thru Paint  
Refinish



Wing nsf

Dented  
With Paint Damage  
Repair and Refinish



**Screen Front**

Chipped  
UpTo 10mm  
Smart Repair



**Door Mirror Assy nsf**

Scratched (Painted)  
Over 25mm Thru Paint  
Smart Repair



**Door nsf**  
Dented  
With Paint Damage  
Repair and Refinish



**Door nsr**  
Dented  
With Paint Damage  
Repair and Refinish



**Qtr Panel nsr**  
Dented  
With Paint Damage  
Repair and Refinish



**Bumper Rear Moulding**  
Broken  
Needs Replaced  
Replace




**Bumper Rear**  
Scratched  
Over 100mm Thru Paint  
Refinish



**Boot Lid**  
Chipped  
1 To 5  
Smart Repair



**Qtr Panel osr**  
Scratched  
Over 25mm Thru Paint  
Refinish




**Door osr**  
Scratched  
Over 25mm Thru Paint  
Refinish



**Door osf**  
Chipped  
Multiple Chips  
Refinish



**Wing osf**  
Dented  
With Paint Damage  
Repair and Refinish



**Roof**  
Chipped  
1 To 5  
Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing nsf	Dented	With Paint Damage	Repair and Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Door nsf	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Bumper Rear Moulding	Broken	Replace	Replace
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Door osr	Scratched	Over 25mm Thru Paint	Refinish
Door osf	Chipped	Multiple Chips	Refinish
Wing osf	Dented	With Paint Damage	Repair and Refinish
Roof	Chipped	1 To 5	Smart Repair

Vehicle Splat

Splat Key

**S3**  
Scratch/Paint defect 100m +

**D2**  
Dent/damage 30-100mm

**D3**  
Dent/damage 100mm +

**C2**  
Multiple Chips

Comments

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.