

Vehicle Inspection Report

Date Inspected: 19/03/2025 15:29

GX68ZXD Reg: VIN: 6FPPXXMJ2PJM11751



Appraised By: Eastbourne Car Auctions

General Deta	1115					Miscellaneous
	NGER LIMITED 4X4 B TD - 3198cc	Body Type Fuel Type Transmission	Pickup Diesel Auto	Doors Colour Year of MFR Date First Reg	5 Blue 2018 17/09/2018	V5 LocationHereMOT LocationHereMOT Expiry10/10/20No. Keys2
Tyres & Whe	els			Interior Condit	ion	Service History
OSF Depth NSF Depth OSR Depth NSR Depth	6 mm 6 mm 6 mm	Alloys Alloys That Need Tools Spare	Yes Refurb 4 No	Upholstery A Seats F Parcel N Shelf Odour N Comments o	Poor No	Service Yes History Stamps

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	Yes	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	Yes

Damage Assessment



Seat Base Cover osf Torn

Over 3mm Replace



Sill os Rusted Over 5mm Refinish

Door osf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Wing osf Scratched Over 25mm Not Thru Paint

Machine Polish

Wing nsf

Scratched

25mm Not

Thru Paint

Machine

Polish

Over



Bumper Front

Scratched

Over 100mm Thru Paint



Bonnet Chipped

1 To 5 Smart Repair

Door osr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Bumper Rear

Scratched

Over 25mm Not Thru Paint

Machine Polish

Qtr Panel nsr

Dented

With Paint Damage

Repair and Refinish

Door osf Dented With Paint Damage

Repair and Refinish

Door nsr Chipped 1 To 5 Smart Repair

Between 10mm +

Rear Moulding Broken

Door nsf

Over

Machine Polish

Chipped

Wing osf

Refinish Wing nsf Dented

> 30mm Smart Repair

Bumper Needs

Replaced Replace

1 To 5

Repair

Repair

Boot Lid Dented Over 30mm

Repair and Refinish

Scratched

25mm Not Thru Paint

Door nsf

2 Or Less

Dented

10mm Smart









Smart

UpTo









Qtr Panel osr Dented

Over

30mm Repair and

Bumper

Refinish

Rear Chipped

Multiple Chips

Smart Repair



Machine Polish

Door osr

1 To 5

Repair



Smart



25mm Not Thru Paint

Door Mirror Assy nsf

Damage Lines


Component
Seat Base Cover osf
Sill os
Door osf
Wing osf
Bumper Front
Bonnet
Wing nsf
Wing nsf
Door osr
Qtr Panel osr
Bumper Rear Moulding
Bumper Rear
Bumper Rear
Boot Lid
Qtr Panel nsr
Door nsr
Door nsf
Door osf
Door osr
Door nsf
Door nsr
Door Mirror Assy nsf
Wing osf

Severity Over 3mm Over 5mm Over 25mm Not Thru Paint Over 25mm Not Thru Paint Over 100mm Thru Paint 1 To 5 Over 25mm Not Thru Paint Between 10mm + 30mm Over 25mm Not Thru Paint Over 30mm Replace Over 25mm Not Thru Paint **Multiple Chips** Over 30mm With Paint Damage Over 25mm Not Thru Paint Over 25mm Not Thru Paint With Paint Damage 1 To 5 1 To 5 1 To 5 Replace 2 Or Less UpTo 10mm

Repair

Replace Refinish Machine Polish Machine Polish Refinish Smart Repair Machine Polish Smart Repair Machine Polish Repair and Refinish Replace Machine Polish Smart Repair Repair and Refinish Repair and Refinish Machine Polish Machine Polish Repair and Refinish Smart Repair

Smart Repair Smart Repair Replace Smart Repair



Condition

Torn

Rusted

Scratched

Scratched

Scratched

Scratched Dented

Scratched

Dented

Broken

Scratched

Chipped

Dented

Dented

Scratched

Scratched

Dented

Chipped

Chipped

Chipped

Broken

Dented

Chipped

Splat Key

S3
Scratch/Paint defect 100m +
D1
Dent/damage under 30mm
D2
Dent/damage 30-100mm
D3
Dent/damage 100mm +
C2
Multiple Chips
R
Rust

£100 ADDITIONAL FEE Last Service - 08/07/2021 at 59,099 miles (4 MAIN DEALER SERVICES)

front bumper misaligned. eml, abs and traction control light on.esc service. hill descent and pre collision fault

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.