

Vehicle Inspection Report

Date Inspected: 24/03/2025 17:09

Reg: YB17ECF

VIN: U5YPK815VHL301575

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	KIA	Body Type	Estate	Doors	5
Model	SPORTAGE GTLINE ED CRDI I - 1685cc	Fuel Type	Diesel	Colour	Red
Mileage	90,206 miles	Transmission	Auto	Year of MFR	2017
				Date First Reg	09/05/2017

Miscellaneous

V5 Location	
No. Keys	1

Tyres & Wheels

OSF Depth	4 mm	Alloys	
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	Space Saver

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No
History
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment

Bumper Front

Scratched

Over
25mm Not
Thru Paint


Machine
Polish

Bumper Front

Chipped

Multiple
Chips

Smart
Repair



Bonnet

Chipped

1 To 5

Smart
Repair



Wing nsf
Dented
With Paint Damage
Repair and Refinish



Door nsf
Dented
With Paint Damage
Repair and Refinish



Door nsr
Dented
With Paint Damage
Repair and Refinish

Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Qtr Panel nsr
Dented
Between 10mm + 30mm
Smart Repair

Bumper Rear
Scratched
Over 25mm Not Thru Paint
Machine Polish



Bumper Rear
Scratched
25 to 100mm Thru Paint
Smart Repair

Boot Lid
Scratched
Over 25mm Not Thru Paint
Machine Polish

Qtr Panel osr
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door osr
Dented
With Paint Damage
Repair and Refinish

Door osf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door osf
Chipped
1 To 5
Smart Repair



Wing osf
Chipped
1 To 5
Smart Repair

Wing osf
Scratched
Over 25mm Not Thru Paint
Machine Polish

Damage Lines			
Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Wing nsf	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Dented	Between 10mm + 30mm	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Dented	With Paint Damage	Repair and Refinish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D1
Dent/damage under 30mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE</p> <p>oil light on</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>