

Vehicle Inspection Report

Date Inspected: 24/03/2025 15:34

Reg: LN17RZG

VIN: SJNFAAZE0U6064370

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	NISSAN	Body Type	Hatchback	Doors	5
Model	LEAF BLACK EDITION - 0cc	Transmission	Auto	Colour	White
Mileage	53,293 miles	Year of MFR	2017	Date First Reg	30/04/2017

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	3 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No History Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	Yes
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	No
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No



Bonnet

Chipped

1 To 5

Smart
Repair

Bumper Front

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper Front

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Roof

Dented

Between
10mm +
30mm

Smart
Repair



Door nsf

Dented

Over
30mm

Repair
and
Refinish



Door nsr

Dented

With Paint
Damage

Repair
and
Refinish



Qtr Panel nsr

Dented

With Paint
Damage

Repair
and
Refinish

Bumper Rear

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Bumper Rear

Scratched

25 to
100mm
Thru Paint

Smart
Repair

Boot Lid

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Qtr Panel osr

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osf

Poor
Previous
Repair

Poor Paint
Refinish



Door osr

Poor
Previous
Repair

Poor Paint
Refinish



Wing osf

Poor
Previous
Repair

Poor Paint
Refinish

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Roof	Dented	Between 10mm + 30mm	Smart Repair
Door nsf	Dented	Over 30mm	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Poor Previous Repair	Poor Paint	Refinish
Door osr	Poor Previous Repair	Poor Paint	Refinish
Wing osf	Poor Previous Repair	Poor Paint	Refinish

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

D1
Dent/damage under 30mm

D3
Dent/damage 100mm +

C2
Multiple Chips

PP
Poor Previous

Comments
<p>£100 ADDITIONAL FEE</p> <p>front bumper misaligned</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>