

Vehicle Inspection Report

Date Inspected: 24/04/2025 10:52

Reg: EY18LYT

VIN: W0VZT6EB4J1152327



Appraised By: Eastbourne Car Auctions

Make VAUXHALL Model INSIGNIA ELITE NAV TURBO - 1490cc Mileage 39,858 miles		Body Type Fuel Type Transmission Gears	Hatchbae Petrol Manual 6	Doors Colour Year of MFR Date First Reg	5 V5 Loc. Blue No. Ke 2018 31/05/2018			
Tyres & W	Vheels				Interior Condi	ition	Service	History
OSF Dep NSF Dep OSR Dep NSR Dep	oth (	5 mm 6 mm 6 mm 6 mm	Alloys Alloys That Need Refurb Tools Spare	Yes 4 Yes Space Saver	Carpets Upholstery Seats Parcel Shelf Odour	Averaç Averaç Averaç f Yes No	ge Histo	-
Extras								
Metallic I Air Condi Stereo Keyless I Phone Ki	ditioning Entry	Yes Radio No	Sun Roof Sat Nav Towbar	Yes No Built In No Yes	terior ec Windows uise umber of Seats eversing Camera	Leather 4 Yes 5 Yes	Electric Seats Heated Seats Xenons Parking Sensors EML	No Yes No Front & Rear No



Rear Scratched Over 100mm

Bumper

Thru Paint Refinish



Boot Lid Scratched Over 25mm Thru Paint Refinish



**Qtr Panel nsr** Dented With Paint Damage

Repair and Refinish

#### Wing nsf

Scratched

Over 25mm Not





Multiple Chips Refinish Wing nsf

Door nsr

Chipped

Chipped 1 To 5 Smart Repair





## Door nsf Chipped Multiple Chips

Refinish

Screen Front Chipped Over 10mm Replace

Bonnet Scratched

Over 25mm Not Thru Paint

Thru Paint

Machine Polish

Machine Polish



Chipped

Multiple Chips

Smart Repair

## Door osf

Scratched

Over 25mm Not Thru Paint

Machine Polish

## Door osr

Chipped 1 To 5 Smart





Repair



Poor Previous Repair

Flake Refinish

Paint

Bonnet Chipped 1 To 5 Smart Repair

Wing osf

Scratched

25mm Not

Thru Paint

Machine

Door osf

Chipped

1 To 5

Smart

Repair

**Qtr Panel** 

Scratched

25mm Not

Thru Paint

Machine

Polish

osr

Over

Polish

Over



Front Scratched 25 to 100mm Thru Paint Smart

Repair

Bumper

# Wing osf Chipped 1 To 5 Smart Repair

Door osr

Scratched Over 25mm Not

Machine Polish

Smart Repair













# Thru Paint

**Qtr Panel** osr

Dented 2 Or Less

UpTo

10mm




Damage Lines

Component Condition **Bumper Rear** Scratched Boot Lid Scratched Qtr Panel nsr Dented Door nsr Chipped Door nsf Chipped Wing nsf Scratched Wing nsf Chipped Screen Front Chipped Bonnet Scratched Bonnet Chipped **Bumper Front** Scratched **Bumper Front** Chipped Wing osf Scratched Wing osf Chipped Door osf Scratched Door osf Chipped Door osr Scratched Door osr Chipped Qtr Panel osr Scratched Qtr Panel osr Dented Poor Previous Repair

Severity Over 100mm Thru Paint Over 25mm Thru Paint With Paint Damage **Multiple Chips Multiple Chips** Over 25mm Not Thru Paint 1 To 5 Over 10mm Over 25mm Not Thru Paint 1 To 5 25 to 100mm Thru Paint **Multiple Chips** Over 25mm Not Thru Paint 1 To 5 Over 25mm Not Thru Paint 1 To 5 Over 25mm Not Thru Paint 1 To 5 Over 25mm Not Thru Paint 2 Or Less UpTo 10mm Paint Flake

Repair Refinish Refinish Repair and Refinish Refinish Refinish Machine Polish Smart Repair Replace Machine Polish Smart Repair Smart Repair Smart Repair Machine Polish Smart Repair Machine Polish Smart Repair Machine Polish Smart Repair Machine Polish Smart Repair Refinish



Splat Key

Scratch/Paint defect 30-100mm Scratch/Paint defect 100m + Dent/damage under 30mm Dent/damage 30-100mm **Multiple Chips** Poor Previous

### Comments

Roof

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.