

Vehicle Inspection Report

Date Inspected: 26/03/2025 12:45

Reg: YP09BSY

VIN: WP0ZZZ99Z9S748771

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

Make	PORSCHE	Body Type	Convertible	Doors	2
Model	911 CARRERA 4S PDK S-A - 3797cc	Fuel Type	Petrol	Colour	Red
Mileage	unknown miles	Transmission	Auto	Year of MFR	2009
				Date First Reg	05/06/2009

Miscellaneous

V5 Location	
MOT Location	Here
MOT Expiry	09/09/2025

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No	
History	
Stamps	

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No

Damage Assessment



Wing osf

Chipped
1 To 5
Smart
Repair



Wing osf

Scratched
UpTo
25mm
Thru Paint
Smart
Repair



Door
Mirror
Assy osf

Scratched
(Painted)
UpTo
25mm
Thru Paint
Smart
Repair



**Qtr Panel
osr**

Scratched

UpTo
25mm
Thru Paint

Smart
Repair



Lamp nsr

Broken

Needs
Replaced

Replace



**Qtr Panel
nsr**

Scratched

Over
25mm
Thru Paint

Refinish



Door nsf

Chipped

Edge Chip

Smart
Repair



**Door
Mirror
Assy nsf**

Scratched
(Painted)

UpTo
25mm
Thru Paint

Smart
Repair




Wing nsf

Scratched

UpTo
25mm
Thru Paint

Smart
Repair




**Bumper
Front**

Scratched

Over
100mm
Thru Paint

Refinish



Bonnet

Poor
Previous
Repair

Paint
Flake

Refinish




**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair



Wing osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Door osf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Qtr Panel
osr**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Bumper
Rear**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish




Door nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



Wing nsf

Scratched

Over
25mm Not
Thru Paint

Machine
Polish

Damage Lines			
Component	Condition	Severity	Repair
Wing osf	Chipped	1 To 5	Smart Repair
Wing osf	Scratched	UpTo 25mm Thru Paint	Smart Repair
Door Mirror Assy osf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Qtr Panel osr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Lamp nsr	Broken	Replace	Replace
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Door nsf	Chipped	Edge Chip	Smart Repair
Door Mirror Assy nsf	Scratched (Painted)	UpTo 25mm Thru Paint	Smart Repair
Wing nsf	Scratched	UpTo 25mm Thru Paint	Smart Repair
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Bonnet	Poor Previous Repair	Paint Flake	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

S1

Scratch/Paint defect to 30mm

S2

Scratch/Paint defect 30-100mm

C2

Multiple Chips

PP

Poor Previous

Comments
<p>No Key . Being sold on behalf of the High Court . Mileage at last Mot 72548 miles</p> <p>unknown if any lights on dash,roof marked and stained,all panels faded,car has no keys</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>