

Brampton House 46 Brampton Road Eastbourne, East Sussex BN22 9BN T:01323 520295 F:01323 520330

#### **Vehicle Inspection Report**

Date Inspected: 24/03/2025 12:41

GY69XHD Reg:

VIN: JN1JGAT32U0050283 NAMA Grading



Grade

Appraised By: Eastbourne Car Auctions

#### General Details

NISSAN Make Model X-TRAIL N-

CONNECTA DIG-T -

1332cc

Mileage 47,244 miles

**Body Type Fuel Type** 

**Transmission** 

Estate Petrol Auto

Doors

Colour Blue Year of MFR 2019

**Date First Reg** 30/10/2019

5

#### Miscellaneous

**V5** Location Here MOT Location Here

**MOT Expiry** 16/07/2025

No. Keys

### Tyres & Wheels

**NSR Depth** 

**OSF Depth** 5 mm **NSF Depth** 5 mm **OSR Depth** 5 mm

5 mm

Yes

Yes

**Alloys Alloys That Need** Refurb

Tools **Spare** 

No Spare

Yes

No

### Interior Condition

Odour

Carpets Average Upholstery Average Seats Average Parcel Shelf No

No

7

Yes

### Service History

Service Yes History **Stamps** 

#### Extras

**Metallic Paint Air Conditioning** Stereo

Radio **Keyless Entry** Yes Yes

**Phone Kit** 

**Central Locking** 

Sun Roof Sat Nav Towbar

**Drv Airbag** 

Yes

Yes

Built In

No Yes Interior **Elec Windows** 

Cruise Number of Seats

**Reversing Camera** 

**Electric Seats** 

4 **Heated Seats** Yes Xenons

> **Parking Sensors EML**

Front & Rear No

No

No

Nο

### Damage Assessment

Bumper **Front** 

Scratched

Over 25mm Not Thru Paint

Machine Polish



Bumper Front

Scratched

25 to 100mm Thru Paint

Smart Repair



**Bonnet** 

Chipped

1 To 5

Smart Repair

Door osf

Scratched

Over

Door osr

Scratched

Over



Wing osf Chipped 1 To 5 Smart Repair





Machine Polish



Door osr

Chipped

1 To 5

Smart Repair



Over 25mm Not Thru Paint

Machine Polish



### Bumper Rear

Scratched

25 to 100mm Thru Paint

Smart Repair

# Bumper Rear

Scratched

Over 25mm Not Thru Paint

Machine Polish



Scratched

Over 25mm Not Thru Paint

Machine Polish



# Qtr Panel nsr

Scratched

Over 25mm Not Thru Paint

Machine Polish



## Qtr Panel nsr

Chipped

1 To 5

Smart Repair



#### Door nsr

Dented

With Paint Damage

Repair and Refinish



# Door nsf

Dented

With Paint Damage

Repair and Refinish



# Wing nsf


Dented

Over 30mm

Repair and Refinish

## Damage Lines

Component	Condition	Severity	Repair
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	25 to 100mm Thru Paint	Smart Repair
Bonnet	Chipped	1 To 5	Smart Repair
Wing osf	Chipped	1 To 5	Smart Repair
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Chipped	1 To 5	Smart Repair
Qtr Panel osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Dented	Over 30mm	Repair and Refinish



## Splat Key

S2

Scratch/Paint defect 30-100mm

D

Dent/damage 100mm +

C2

Multiple Chips

#### Comments

£65 ADDITIONAL FEE. Last Service - 03/07/2024 at 40,787 miles (1 main dealer service)

eml and traction control light on.gearbox/engine judder and crash dection system fault

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.