

Vehicle Inspection Report

Date Inspected: 25/03/2025 11:23

**Reg:** KT16LVE

**VIN:** YV1LF68BCH1113107

NAMA Grading



Grade

3

Appraised By: Eastbourne Car Auctions

General Details

<b>Make</b>	VOLVO	<b>Body Type</b>	Estate	<b>Doors</b>	5
<b>Model</b>	XC90 R-DESIGN D5 P-PULSE - 1969cc	<b>Fuel Type</b>	Diesel	<b>Colour</b>	Silver
<b>Mileage</b>	126,331 miles	<b>Transmission</b>	Auto	<b>Year of MFR</b>	2016
				<b>Date First Reg</b>	29/06/2016

Miscellaneous

<b>V5 Location</b>	Here
<b>MOT Location</b>	Here
<b>MOT Expiry</b>	05/06/2025
<b>No. Keys</b>	2

Tyres & Wheels

<b>OSF Depth</b>	4 mm	<b>Alloys</b>	Yes
<b>NSF Depth</b>	4 mm	<b>Alloys That Need Refurb</b>	4
<b>OSR Depth</b>	4 mm	<b>Tools</b>	No
<b>NSR Depth</b>	4 mm	<b>Spare</b>	No Spare

Interior Condition






<b>Carpets</b>	Good
<b>Upholstery</b>	Good
<b>Seats</b>	Average
<b>Parcel Shelf</b>	No
<b>Odour</b>	No

Service History

**Service History**  
Stamps

Extras

<b>Metallic Paint</b>	Yes	<b>Central Locking</b>	Yes	<b>Interior</b>	Half Leather	<b>Electric Seats</b>	Yes
<b>Air Conditioning</b>	Yes	<b>Sun Roof</b>	No	<b>Elec Windows</b>	4	<b>Heated Seats</b>	Yes
<b>Stereo</b>	Radio	<b>Sat Nav</b>	Built In	<b>Cruise</b>	Yes	<b>Xenons</b>	No
<b>Keyless Entry</b>	No	<b>Towbar</b>	No	<b>Number of Seats</b>	7	<b>Parking Sensors</b>	Front & Rear
<b>Phone Kit</b>	Yes	<b>Drv Airbag</b>	Yes	<b>Reversing Camera</b>	Yes	<b>EML</b>	No

	<b>Bonnet</b>		<b>Bumper Front</b>		<b>Bumper Front</b>
	Scratched		Scratched		Chipped
	Over 25mm Not Thru Paint		Over 25mm Not Thru Paint		Multiple Chips
	Machine Polish		Machine Polish		Smart Repair
	<b>Wing osf</b>		<b>Door osf</b>		<b>Door osr</b>
	Scratched		Scratched		Scratched
	Over 25mm Not Thru Paint		Over 25mm Not Thru Paint		Over 25mm Not Thru Paint
	Machine Polish		Machine Polish		Machine Polish
	<b>Door osr</b>		<b>Bumper Rear</b>		<b>Bumper Rear</b>
	Scratched		Scratched		Scratched
	UpTo 25mm Thru Paint		Over 25mm Not Thru Paint		25 to 100mm Thru Paint
	Smart Repair		Machine Polish		Smart Repair
	<b>Qtr Panel nsr</b>		<b>Door nsr</b>		<b>Door nsf</b>
	Dented		Dented		Chipped
	With Paint Damage		With Paint Damage		Multiple Chips
	Repair and Refinish		Repair and Refinish		Refinish
	<b>Wing nsf</b>				
	Scratched				
	Over 25mm Not Thru Paint				
	Machine Polish				

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osr	Scratched	UpTo 25mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Chipped	Multiple Chips	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish

Vehicle Splat

Splat Key

**S1**  
Scratch/Paint defect to 30mm

**S2**  
Scratch/Paint defect 30-100mm

**D2**  
Dent/damage 30-100mm

**C2**  
Multiple Chips

Comments
<p>£65 ADDITIONAL FEE. Last Service - 06/06/2024 at 118,219 miles (7 main dealer services)</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>