

Vehicle Inspection Report

Date Inspected: 25/03/2025 11:09

Reg: LG20VLM

VIN: 5YJ3F7EBXLF703352

NAMA Grading



Grade

1

Appraised By: Eastbourne Car Auctions

General Details

Make	TESLA	Body Type	Hatchback	Doors	5
Model	MODEL 3 LONG RANGE AWD - 0cc	Transmission	Auto	Colour	Grey
Mileage	10,486 miles	Year of MFR	2020	Date First Reg	29/05/2020

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	No Spare

Interior Condition




Carpets	Good
Upholstery	Good
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No History Stamps


Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	Yes
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment				
	Bonnet Scratched Over 25mm Not Thru Paint Machine Polish		Bumper Front Scratched Over 25mm Not Thru Paint Machine Polish	Bumper Front Chipped Multiple Chips Smart Repair
	Wing nsf Scratched Over 25mm Not Thru Paint Machine Polish		Door nsf Scratched Over 25mm Not Thru Paint Machine Polish	Door nsr Scratched Over 25mm Not Thru Paint Machine Polish
	Bumper Rear Scratched Over 25mm Not Thru Paint Machine Polish		Bumper Rear Scratched 25 to 100mm Thru Paint Smart Repair	Boot Lid Scratched Over 25mm Not Thru Paint Machine Polish
	Qtr Panel osr Chipped 1 To 5 Smart Repair		Door osr Scratched Over 25mm Not Thru Paint Machine Polish	 Door osf Chipped 1 To 5 Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Front	Chipped	Multiple Chips	Smart Repair
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Chipped	1 To 5	Smart Repair
Door osr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Chipped	1 To 5	Smart Repair

Vehicle Splat



Splat Key

S2

Scratch/Paint defect 30-100mm

C2

Multiple Chips

Comments

£65 ADDITIONAL FEE.

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.