



Vehicle Inspection Report

Date Inspected: 27/03/2025 10:01

Reg: LD60XZM

WMWSU32020TY97331 VIN:

NAMA Grading



Grade

Appraised By: Eastbourne Car Auctions

Genera		

Make MINI Model COOPER - 1598cc

Mileage 90,735 miles

Body Type

Hatchback Petrol **Fuel Type Transmission** Manual

Gears

3 **Doors**

Colour Red Year of MFR 2010

Date First Reg 13/12/2010 Miscellaneous

V5 Location Here MOT Location Here

MOT Expiry 06/01/2026

No. Keys

Tyres & Wheels

NSR Depth

OSF Depth 5 mm **NSF** Depth **OSR Depth**

2 mm 5 mm

5 mm

Refurb Tools **Spare**

Alloys

Yes **Alloys That Need** 4

> No No

> > Spare

Interior Condition

Carpets Average Upholstery Average Seats Average Parcel Shelf Yes Odour No

Service History

Service Yes History **Stamps**

Extras

Metallic Paint No Yes Interior Half Leather **Electric Seats Central Locking** No **Air Conditioning** 2 Yes Sun Roof **Elec Windows Heated Seats** No No Sat Nav Cruise Stereo Radio No Yes Xenons No **Parking Sensors Keyless Entry** No **Towbar** No **Number of Seats** 4 No **Phone Kit Drv Airbag Reversing Camera EML** No Yes No No

Damage Assessment



Bumper Rear

Poor Previous Repair

Paint Flake

Refinish



Boot Lid

Poor Previous Repair

Poor Paint

Refinish



Qtr Panel osr

Poor Previous Repair

Poor Paint

Refinish



Door osf

Poor Previous Repair

Paint Flake

Refinish



Wing osf

Poor Previous Repair

Poor Paint

Refinish



Bonnet

Poor Previous Repair

Paint Flake

Refinish



Bumper Front

Scratched

Over 25mm Not Thru Paint

Machine Polish

Bumper Front

Chipped

Multiple

Smart

Repair



Chips

Qtr Panel nsr

Poor Previous Repair

Paint Flake

Refinish

Wing nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish



Scratched

Over 25mm Not Thru Paint

Machine Polish



Door nsf

Poor Previous Repair

Paint Flake

Refinish

Screen Front

Chipped

UpTo 10mm

Smart Repair

Damage Lines


Roof

Screen Front

Condition	Severity	Repair
Poor Previous Repair	Paint Flake	Refinish
Poor Previous Repair	Poor Paint	Refinish
Poor Previous Repair	Poor Paint	Refinish
Poor Previous Repair	Paint Flake	Refinish
Poor Previous Repair	Poor Paint	Refinish
Poor Previous Repair	Paint Flake	Refinish
Scratched	Over 25mm Not Thru Paint	Machine Polish
Chipped	Multiple Chips	Smart Repair
Scratched	Over 25mm Not Thru Paint	Machine Polish
Poor Previous Repair	Paint Flake	Refinish
Poor Previous Repair	Paint Flake	Refinish
	Poor Previous Repair Scratched Chipped Scratched Poor Previous Repair	Poor Previous Repair Paint Flake Scratched Over 25mm Not Thru Paint Chipped Scratched Over 25mm Not Thru Paint Poor Previous Repair Paint Flake

Over 25mm Not Thru Paint

UpTo 10mm



Splat Key

C2

Multiple Chips

Machine Polish

Smart Repair

PP

Poor Previous

Comments

£65 ADDITIONAL FEE. Last Service - 25.02.2023 at 73430 miles (7 services)

Scratched

Chipped

gearstick cap broken

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.