

Vehicle Inspection Report

Date Inspected: 27/03/2025 14:54

GU16FUV Reg:

VIN: JN1TCNT32U0016467



Appraised By: Eastbourne Car Auctions

General	Details						Miscellaneous	
Make	NISSAN		Body Type	Estate	Doors	5	V5 Location	
Model	X-TRAIL 1	TEKNA DCI	Fuel Type	Diesel	Colour	Black	No. Keys	2
4X4 - 1598cc		98cc	Transmission	Manual	Year of MFR	2016		
Mileage 110,032 miles		miles	Gears	6	Date First Reg	16/03/2016		
Tyres & ^v	Wheels				Interior Condit	tion	Service History	
Tyres & ^v OSF De		5 mm	Alloys	Yes		tion Average	Service History Service No	
	pth	5 mm 5 mm	Alloys Alloys That Need			Average		
OSF De	pth pth		-		Carpets A Upholstery A	Average	Service No	
OSF De NSF De	pth pth pth	5 mm	Alloys That Need		Carpets A Upholstery A Seats A	Average Average	Service No History	

Odour

No Comments both front seats

heavily worn

Saver

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Leather	Electric Seats	Yes
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	Yes
Keyless Entry	Yes	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Chipped

Bonnet

Multiple Chips Refinish Bumper Front

> Scratched Over 25mm Not

Thru Paint Machine

Polish



Bumper Front

Chipped

Multiple Chips

Smart Repair

Wing osf Scratched Over 25mm Not Thru Paint

Machine Polish



Door osf Poor Previous Repair

Refinish

Boot Lid

Poor Previous

Repair

Paint

Flake

Refinish

Poor Paint





Qtr Panel nsr Scratched Over 25mm Thru Paint



Refinish



Door nsf Poor

Previous Repair Paint

Flake Refinish

Roof

Scratched Over 25mm Not Thru Paint

Machine Polish



Wing osf

1 To 5 Smart Repair

Chipped

Door osr Poor Previous Repair Poor Paint

Refinish

Bumper Rear Scratched Over 25mm Not



Door nsr Chipped Multiple Chips Refinish

Wing nsf

Scratched Over 25mm Not Thru Paint Machine

Polish

Screen Front Chipped UpTo 10mm

Smart Repair

Thru Paint Machine Polish

25mm Not

Over

Qtr Panel osr

Scratched

Over 25mm Not Thru Paint

Machine Polish

Bumper Rear

Chipped

Multiple Chips

Smart Repair

Door nsf

Scratched

Over 25mm Not Thru Paint

Machine Polish

Wing nsf

Chipped

1 To 5

Smart Repair

Damage Lines

Component	Condition
Bonnet	Chipped
Bumper Front	Scratched
Bumper Front	Chipped
Wing osf	Scratched
Wing osf	Chipped
Wing osf	Scratched
Door osf	Poor Previous Repair
Door osr	Poor Previous Repair
Qtr Panel osr	Scratched
Boot Lid	Poor Previous Repair
Bumper Rear	Scratched
Bumper Rear	Chipped
Qtr Panel nsr	Scratched
Door nsr	Chipped
Door nsf	Scratched
Door nsf	Poor Previous Repair
Wing nsf	Scratched
Wing nsf	Chipped
Roof	Scratched
Screen Front	Chipped


Severity

Multiple Chips Over 25mm Not Thru Paint **Multiple Chips** Over 25mm Not Thru Paint 1 To 5 Over 25mm Not Thru Paint Poor Paint Poor Paint Over 25mm Not Thru Paint Paint Flake Over 25mm Not Thru Paint Multiple Chips Over 25mm Thru Paint **Multiple Chips** Over 25mm Not Thru Paint Paint Flake Over 25mm Not Thru Paint 1 To 5 Over 25mm Not Thru Paint UpTo 10mm

Repair

Refinish Machine Polish Smart Repair Machine Polish Smart Repair Machine Polish Refinish Refinish Machine Polish Refinish Machine Polish Smart Repair Refinish Refinish Machine Polish Refinish Machine Polish Smart Repair Machine Polish Smart Repair

Vehicle Splat



Splat Key

S2 Scratch/Paint defect 30-100mm C2 Multiple Chips PP Poor Previous

Comments

nsf wheel arch trim insecure and wnginw noisy. gearbox/transfer box whine. parking sensor system fault

No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.