

Vehicle Inspection Report

Date Inspected: 28/03/2025 12:45

Reg: YH67XOV

VIN: TSMJYA02S00514483

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	SUZUKI	Body Type	Hatchback	Doors	5
Model	SX4 S-CROSS SZ4 BOOSTERJE - 998cc	Fuel Type	Petrol	Colour	Black
Mileage	94,659 miles	Transmission	Manual	Year of MFR	2017
		Gears	5	Date First Reg	20/10/2017

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	No
NSR Depth	5 mm	Spare	Inflation Kit

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	No
Odour	No

Service History

Service No  
History  
Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	4	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	No	EML	No



**Bonnet**  
Chipped  
1 To 5  
Smart  
Repair



**Bumper  
Front**  
Poor  
Previous  
Repair  
Poor Paint  
Refinish



**Wing nsf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door nsf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door nsf**  
Chipped  
1 To 5  
Smart  
Repair



**Door nsr**  
Scratched  
Over  
25mm  
Thru Paint  
Refinish



**Qtr Panel  
nsr**  
Scratched  
Over  
25mm  
Thru Paint  
Refinish



**Bumper  
Rear**  
Scratched  
Over  
100mm  
Thru Paint  
Refinish



**Boot Lid**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Qtr Panel  
osr**  
Poor  
Previous  
Repair  
Poor Paint  
Refinish



**Door osr**  
Poor  
Previous  
Repair  
Poor Paint  
Refinish



**Door osf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Door osf**  
Dented  
2 Or Less  
UpTo  
10mm  
Smart  
Repair



**Wing osf**  
Scratched  
Over  
25mm Not  
Thru Paint  
Machine  
Polish



**Screen  
Front**  
Chipped  
UpTo  
10mm  
Smart  
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	1 To 5	Smart Repair
Bumper Front	Poor Previous Repair	Poor Paint	Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door nsf	Chipped	1 To 5	Smart Repair
Door nsr	Scratched	Over 25mm Thru Paint	Refinish
Qtr Panel nsr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel osr	Poor Previous Repair	Poor Paint	Refinish
Door osr	Poor Previous Repair	Poor Paint	Refinish
Door osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door osf	Dented	2 Or Less UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Screen Front	Chipped	UpTo 10mm	Smart Repair

Vehicle Splat

Splat Key

**S2**  
Scratch/Paint defect 30-100mm

**S3**  
Scratch/Paint defect 100m +

**D1**  
Dent/damage under 30mm

**C2**  
Multiple Chips

**PP**  
Poor Previous

Comments
<p>£65 ADDITIONAL FEE.</p> <p>squeaky belt and rough running</p> <p><b>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</b></p>