

Vehicle Inspection Report

Date Inspected: 10/04/2025 12:39

Reg: FN12WRX

VIN: WMWSW32050T214631

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	MINI	Body Type	Hatchback	Doors	3
Model	COOPER D - 1598cc	Fuel Type	Diesel	Colour	Red
Mileage	98,485 miles	Transmission	Manual	Year of MFR	2012
		Gears	6	Date First Reg	04/03/2012

Miscellaneous

V5 Location	
No. Keys	2

Tyres & Wheels

OSF Depth	4 mm	Alloys	Yes
NSF Depth	4 mm	Alloys That Need Refurb	4
OSR Depth	4 mm	Tools	No
NSR Depth	4 mm	Spare	No Spare

Interior Condition

Carpets	Average
Upholstery	Average
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service No History Stamps

Extras

Metallic Paint	No	Central Locking	Yes	Interior	Half Leather	Electric Seats	No
Air Conditioning	Yes	Sun Roof	No	Elec Windows	2	Heated Seats	No
Stereo	Radio	Sat Nav	No	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	4	Parking Sensors	No
Phone Kit	No	Drv Airbag	Yes	Reversing Camera	No	EML	No



Bonnet
Dented
With Paint Damage
Repair and Refinish



Bumper Front
Scratched
Over 100mm Thru Paint
Refinish



Wing osf
Poor Previous Repair
Paint Flake
Refinish



Screen Front
Chipped
UpTo 10mm
Smart Repair



Door osf
Chipped
Multiple Chips
Refinish



Qtr Panel osr
Dented
Over 30mm
Repair and Refinish



Bumper Rear
Scratched
25 to 100mm Thru Paint
Smart Repair



Bumper Rear
Scratched
Over 25mm Not Thru Paint
Machine Polish



Boot Lid
Chipped
1 To 5
Smart Repair



Qtr Panel nsr
Dented
With Paint Damage
Repair and Refinish



Door nsf
Dented
With Paint Damage
Repair and Refinish



Wing nsf
Scratched
Over 25mm Not Thru Paint
Machine Polish



Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint
Smart Repair



Roof
Dented
Between 10mm + 30mm
Smart Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Dented	With Paint Damage	Repair and Refinish
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Wing osf	Poor Previous Repair	Paint Flake	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Door osf	Chipped	Multiple Chips	Refinish
Qtr Panel osr	Dented	Over 30mm	Repair and Refinish
Bumper Rear	Scratched	25 to 100mm Thru Paint	Smart Repair
Bumper Rear	Scratched	Over 25mm Not Thru Paint	Machine Polish
Boot Lid	Chipped	1 To 5	Smart Repair
Qtr Panel nsr	Dented	With Paint Damage	Repair and Refinish
Door nsf	Dented	With Paint Damage	Repair and Refinish
Wing nsf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Door Mirror Assy nsf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Roof	Dented	Between 10mm + 30mm	Smart Repair

Vehicle Splat

Splat Key

S2
Scratch/Paint defect 30-100mm

S3
Scratch/Paint defect 100m +

D1
Dent/damage under 30mm

D2
Dent/damage 30-100mm

D3
Dent/damage 100mm +

C2
Multiple Chips

PP
Poor Previous

Comments
<p>£65 ADDITIONAL FEE.</p> <p>clutch/gearbox issue</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>