

Vehicle Inspection Report

Date Inspected: 01/04/2025 11:30

Reg: GY67DWJ

VIN: WVGZZZ5NZJW328019

NAMA Grading



Grade

4

Appraised By: Eastbourne Car Auctions

General Details

Make	VOLKSWAGEN	Body Type	Estate	Doors	5
Model	TIGUAN SEL TSI BMT 4MOTIO - 1984cc	Fuel Type	Petrol	Colour	Blue
Mileage	84,651 miles	Transmission	Auto	Year of MFR	2017
				Date First Reg	18/10/2017

Miscellaneous

V5 Location	Here
MOT Location	Here
MOT Expiry	13/07/2025
No. Keys	2

Tyres & Wheels

OSF Depth	5 mm	Alloys	Yes
NSF Depth	5 mm	Alloys That Need Refurb	4
OSR Depth	5 mm	Tools	Yes
NSR Depth	5 mm	Spare	Space Saver

Interior Condition

Carpets	Good
Upholstery	Good
Seats	Average
Parcel Shelf	Yes
Odour	No

Service History

Service History Stamps

Extras

Metallic Paint	Yes	Central Locking	Yes	Interior	Cloth	Electric Seats	No
Air Conditioning	Yes	Sun Roof	Yes	Elec Windows	4	Heated Seats	Yes
Stereo	Radio	Sat Nav	Built In	Cruise	Yes	Xenons	No
Keyless Entry	No	Towbar	No	Number of Seats	5	Parking Sensors	Front & Rear
Phone Kit	Yes	Drv Airbag	Yes	Reversing Camera	Yes	EML	No

Damage Assessment



Bonnet

Chipped
Multiple Chips
Refinish



Bumper Front Moulding

Broken
Needs Replaced
Replace



Bumper Front

Scratched
Over 100mm Thru Paint
Refinish

Wing osf

Scratched
Over 25mm Not Thru Paint



**Screen
Front**

Chipped

UpTo
10mm

Smart
Repair

Machine
Polish



Wing osf

Dented

2 Or Less
UpTo
10mm

Smart
Repair



**Door
Mirror
Assy osf**

Scratched
(Painted)

Over
25mm
Thru Paint

Smart
Repair



Door osf

Poor
Previous
Repair

Poor Paint
Refinish



Door osr

Poor
Previous
Repair

Poor Paint
Refinish



**Qtr Panel
osr**

Scratched

Over
25mm
Thru Paint
Refinish



**Bumper
Rear**

Scratched

Over
100mm
Thru Paint
Refinish



Boot Lid

Dented

2 Or Less
UpTo
10mm

Smart
Repair

**Qtr Panel
nsr**

Scratched

Over
25mm Not
Thru Paint

Machine
Polish



**Qtr Panel
nsr**

Chipped

1 To 5

Smart
Repair



Door nsr

Chipped

Multiple
Chips
Refinish



Door nsf

Dented

Over
30mm

Repair
and
Refinish



Wing nsf

Dented

With Paint
Damage

Repair
and
Refinish

Door osr

Dented

Between
10mm +
30mm

Smart
Repair

Damage Lines			
Component	Condition	Severity	Repair
Bonnet	Chipped	Multiple Chips	Refinish
Bumper Front Moulding	Broken	Replace	Replace
Bumper Front	Scratched	Over 100mm Thru Paint	Refinish
Screen Front	Chipped	UpTo 10mm	Smart Repair
Wing osf	Scratched	Over 25mm Not Thru Paint	Machine Polish
Wing osf	Dented	2 Or Less UpTo 10mm	Smart Repair
Door Mirror Assy osf	Scratched (Painted)	Over 25mm Thru Paint	Smart Repair
Door osf	Poor Previous Repair	Poor Paint	Refinish
Door osr	Poor Previous Repair	Poor Paint	Refinish
Qtr Panel osr	Scratched	Over 25mm Thru Paint	Refinish
Bumper Rear	Scratched	Over 100mm Thru Paint	Refinish
Boot Lid	Dented	2 Or Less UpTo 10mm	Smart Repair
Qtr Panel nsr	Scratched	Over 25mm Not Thru Paint	Machine Polish
Qtr Panel nsr	Chipped	1 To 5	Smart Repair
Door nsr	Chipped	Multiple Chips	Refinish
Door nsf	Dented	Over 30mm	Repair and Refinish
Wing nsf	Dented	With Paint Damage	Repair and Refinish
Door osr	Dented	Between 10mm + 30mm	Smart Repair

Vehicle Splat

Splat Key

S3

Scratch/Paint defect 100m +

D1

Dent/damage under 30mm

D3

Dent/damage 100mm +

C2

Multiple Chips

PP

Poor Previous

Comments
<p>£65 ADDITIONAL FEE. Last Service - 10/07/2024 at 74,375 miles (7 services)</p> <p>No mechanical inspection has been undertaken on this vehicle, any mechanical items noted are for reference only and cannot be relied on.</p>